05/CT 23007097/Thps 2026 June ASSIGNMENT Veh No: SDK 8922G. Yr Regn: 2006, June. From: Estimated Cost: Type: M. Ger. I M. Cycle / Bus / Van / Lorry / Taxl / Prime Mover / OD TP/WS/TP RES/OD RES/EVA/INV/MV ·Truck / Traller or To Inspect Vehicle No: 2362. Make: at Workshop.m/s A/G: Insured / Std / NI / NA T/Radio; Insured / Std / NI / NA Sp.ReadIng Insured: Eng/No: Policy No. .C/No: Claims No. Gen. Cond Good / Fair / Poor / Burnt Sum Insured: Sleering: Inorde / Jammed / Leaked / Burnt or (Client's Record) morder / Jammed / Leaked / Bumt or Make of Veh: Modl: NII / SPRim / STD A/Rim or Tyre Size: (Policy-Condition) Remark: The veh had commenced its O/S BS / DUN / EXNOVA / GY LFS / LIZA/ MIDY OHTSU / PIR / SUMI / repair at the time of inspection. Ball or Warket Value: Front Rear IDAC Accident Roort Consistent? : Yes or No R/Bal. R/Bal. mm GIA / PR Seem Consistent? : Yes or No L/Bal. UBal. mm Est. Repairs: days Res.: Yes or No D.O.A. Lum Sum: 3 Val.: Yes or No Survey held at Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop-or CA / 柱V 1 REP. 1 24 HRS Vehicle: IN / OUT Fire case. Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction Dala/Time, File Pass to? : Prell. Report Days Of Repair: : Final Report Resurvey No. of Trlp: Dala/Time, File Rebito to? Survey Fee: Transportation: Add Fee;

:Site insp (\$

: Interview (\$

: Tech, Invs (\$

Meel end (%

Popular:

Lump Sun / Le.E. C.

_\$+RS__ SI

Pholos

l'imans

TOTAL

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 12 Jul 2023)

Parts:

M1-MPV

SDK 89229 OD 1 (hina * Fire case

Labour.

Repairer's

TOYOTA PREVIA 2.4 8-SEATER (A) (Catalogue: Merimen Singapore 1.0) (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SDK8922G/12/07/2023 18:20

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

There are no new parts selected.

Cheng Hoe Motor Pte Ltd/SDK8922G/12/07/2023 18:20. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Lab	our Items		
1	Towing (from scene to Owners own workshop) - by owner	New	120.00
2	Towing (from own workshop to Cheng Hoe,Woodlands)	New	50.00
		Gross Labour Cost (S\$)	170.00

Cheng Hoe Motor Pte Ltd/SDK8922G/12/07/2023 18:20. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufin 97498749/62563561

Mot du Movise

Ex: fobe advise

13/7/23 e 230pm.

taufint ellhanton

15	77828256
7/5	
24 Hours	Towing Services

Efficient Towing Services 402B Fernyale Lane #22-229 Singapore 792402 Ah Di Mobile: 8588 8877

Email: efficientlowing.sg/a/gmail.com Busmess Reg. No.: 53349344K

bistate,

NO. 138571
Date: 12/7/2

CASH SALE / JOB ORDER

	17416 122229
Messos: chang Hoe	Jump Start/Changing of battery
se CON C 年型 Town	Tyre Replacement
Vehicle No. SDK 8720 Model No: Nevra	Accident/Breakdown
对的 (以注)	Multi/Basement
2 1 11	With Load Cargo Box
Location: 10 fen Jury this kan 1700	- King Dolly
11 15 601 05-04	Transport Charge
To: 38 woodard (nd farce) US	Low Body Kit
無疑 450 Jehers:	- Door Opening Service
Cash S Tow Truck //en	Crane Up/Wirch Out
经手人 Authorised By: Ah DY Driver Name:	Collect Doc Key
	Repo
注意,本公司对所施之车辆,在进行中知有任何损失或破坏,	Woodlands and Tras Checkpoint
一概由车主自行负责。	E. S. O. E.
es a fair and of on ner a flak. The company and the being inwest.	NOT THE REPORT OF THE PARTY OF

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	342G
Vehicle Details	
Vehicle No.:	SDK8922G
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jul 2023
Vehicle Make:	TOYOTA
Vehicle Model:	PREVIA 8 SEATER
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	2AZ2231698
Chassis No.:	JTEGD52MX07029721
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$36,202.00
Original Registration Date:	06 Jun 2006
First Registration Date:	06 Jun 2006
Transfer Count:	1
Actual ARF Paid:	\$39,823.00
Intended PARF Rebate Details	\$37,623.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	40.00
COE Expiry Date:	31 May 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$46,048.00
COE Rebate Amount:	\$13,306.00
Total Rebate Amount:	\$13.306.00

The information contained herein is correct as at 10 Jul 2023



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Actual Driver
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this Form by instraince companies is not an admission of panel marks of the part of the instraince of the Police for investigation.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDEN	ITISTATEMENTI A LA L
Date of Submission Reported by Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss	10/07/2023 18:19 (SGT) Both Policyholder and Actual Driver 09/07/2023 02:00 (SGT) Singapore 118A ALKAFF CRESCENT ALKAFF LAKEVIEW UN/LOADING BAY Singapore
DESCRIPTION OF THE PROPERTY OF	F OWN VEHICLE
Vehicle Registration Number	SDK8922G
INSURED/POLICYHOLDER	
Is company? Name Of Registered Owner NRIC No Email Address Mobile Phone No Alternative Phone No	No CHUA KOK WEI SXXXX342G edwinchua8922@gmail.com (Phone) +65-98418922
- VEHICLE PARTICULARS	
Manufacturer Model Variant Exact purpose for which vehicle was being used at time of	Toyota PREVIA 8 SEATER -
accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC	Private use Yes Private car Auto 2362
INSURANCE COMPANY	
Name of Insurance Company Policy Number / Cover Note Number	China Taiping Insurance (Singapore) Pte. Ltd. DMPCSNA00134292215
DRIVER	
Name of Driver NRIC No	SHERMAINE CHUA SI MIN SXXXX813I

SXXXX813I

11/11/1995

Date Of Birth

Occupation Indoor Date Of Driving Pass 23/06/2014 Driving experience 9 YEARS AND 1 MONTH Gender Female Mobile Number (Phone) +65-98758922 Alt. Phone Number Email Address shermainechua15@gmail.com Address BLK 708 CLEMENTI WEST ST. 2 #1-301 Address complement Postcode 120708 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Child Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver erengen verse i timitan energyananan mananan energy i Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Fire, explosion or lightning Weather Conditions Clear Road Surface The second secon OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 1 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? No Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name Gender DETAILS OF POLICE ACTION Was the accident reported to the police? Police Station Name **Tanglin Division Headquaters** Police Station Phone No (Phone) +65-18003910000 (Fax) +65-63964900 Alt. Police Station Phone No 21 Kampong Java Road Singapore 228892 Police Station Address Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO POLICE REPORT ATTACHED. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera?

Describe Circumstance of the Accident "NOTE PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information. (V) Claim Own Policy () Claim Third party () Reporting Only			
() Claim OD/ TP at other workshop () Sketch Plan			
Sketch Plan The scant Lake view Car Park Sport State of			
Refer to Police Report No: E/20230710/7025			
* Vehicle currently at 10 Penjuru Rd - Ang Kah Hoe Automobile Declaration			

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in) RIC/ID card)

SKETCH PLAN

INSURER: China Taiping

DATE OF ACC: 09 7 33 @ 02:00an

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

PLEASE

TIURN

OVER



Report No. E/20230710/7025

POLICE REPORT (NP299)

Police Station Of Origin Tanglin Division HQ 21 Kampong Java Road SINGAPORE 228892

Tel No:1800-3910000

Date/Time Report Made	Vide Repor	t No.		Station Diary No.
10/07/2023 13:52				
Name Of Informant	Address			
SHERMAINE CHUA SI MIN	708 CLEMENTI WEST STREET 2 #11-301 SINGAPORE		I-301 SINGAPORE	
	120708			
ID Type / ID No.	Contact No).		
NRIC NO / S9541813I	Home/Office	e:	Mobile:	
			98758922	
Nationality	Email Address			
SINGAPORE CITIZEN	SHERMAINECHUA15@GMAIL.COM			
Occupation	Sex	Age	Date of Birth	Race
Primary school teacher	Female	27	11/11/1995	Chinese
Institution/School Name	Language			
3	English			
Date/Time Of Incident	Location Of Incident			
09/07/2023 02:00 - 09/07/2023 02:10	118A ALKAFF CRESCENT ALKAFF LAKEVIEW			
	SINGAPOR	RE 341118		

Brief details.

At 2 a.m., I was in the car which was stationary at the loading bay. I saw smoke coming out from the front wheel on the left and immediately turned off the engine and stepped out.

Soon, I saw sparks under the car and called 995. Then I went to find the hdb hose and sprayed water towards the car.

Signature Of Officer Recording The Report:	Signature Of Informant:
Not applicable	The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 10/07/2023 13:52
Officer In-Charge Of Case:	Classification Of Case:





2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20230710/7025

After a couple of minutes, the fire started beneath the car and the fire engine came. While the fireman were putting out the fire, it grew bigger under the bonnet. The engine was burning.

The fire was completely extinguished in 30 minutes.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 10/07/2023 13:52
Officer In-Charge Of Case:	Classification Of Case:
+	4