## Mei Kwan (LKKAuto)

From:	Susan Low < liusbro@ymail.com>
Sent:	Thursday, 13 July 2023 3:54 PM

To: Admin A

**Subject:** Our Ref: YQ1224D230706 Your Ref: SMT1627B

**Attachments:** YQ1224D230706.pdf; YQ1224D Search.pdf

Follow Up Flag: Follow up Flag Status: Flagged

Categories: HMK

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Vehicle to be surveyed:	YQ1224D
3rd Party Insured Vehicle:	SMT1627B
Date of Accident:	06/07/2023
Location of Accident:	TPE Filter To Upper Changi Road East
Name of Workshop:	Liu's Brother Auto Engineering Workshop
Address of Survey Location:	No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki
	Bukit Singapore 417883

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop as soon as possible.

Kindly arrange

Thank.

Best Regards,

Susan Low M/s Liu's Brother Auto Engineering Workshop No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 Tel: 67411730

Date of Survey:	
Name of Authorise Surveyor:	

