

Service Request Details

Claim	S3M04O0N
Reference	CS3/HSB23007126/Kqp3e2 
Loss Date	11 July 2023
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	13 Jul 2023 9:54:37 AM
Request Date	13 July 2023
Due Date	

Actions

Next Step Add invoice

Add Invoice

Vehicle Information

Incident SGG9755B

Vehicle

Registration #

Make TPVD Mazda

Model 3

Service Address

, , ,

Primary Contact/Insured

Services

Pre-Repair Survey

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

LOW Garnet

garnet.low@axa.com.sg

Additional Instructions

Messages2

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

Invoice



Surveyor/ Assessor expense



Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
HSB-LKKInvoice-AC2304699.pdf.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	21 July 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	21 July 2023
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	21 July 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	21 July 2023
 SGG9755B IA.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 July 2023
 OI GIA RPORT - SHA6956C.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	17 July 2023
 REPLY FORM SOLICITOR.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	13 July 2023
 TP GIA REPORT - SGG9755B.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	13 July 2023
 EMAIL FORM SOLICITOR FOR TP	Letters and	Others	NIKAM Santosh	13 July 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
REG.msg.msg	Correspondence		Pandurang	