

ASS. REC. BY:

REF:

17SB/ 2300 7145/1CV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

8163K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2-3 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNG 28906

Yr Regn:

07.22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy

Prius

C.C

1798

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

90484

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTD 8S3E460 J0680386

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

11/7/23

D.O.I.

14/7/2023

Survey held at

11-30am

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

New O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 PRS, no documents given. Unable to search DOR.

EM repair cost 82-3K

Time, File Pass to?

☐

Prel. Report

☐

Final Report

Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

Fees