



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI23007152/Kny3q2

Date: 31/07/2023

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMJ 5771T	Veh. Inspected	GBK 6281J
Policy No.	P10862411R00	Coverage (\$)	0.00
Claim No.	C10023464 /CY	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	14/07/2023

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200 (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JN1YAAM20Z0001185	Colour	SILVER
Odometer	41662 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	165/80 R14	GITI	9 mm
L/H Front Tyre	165/80 R14	GITI	9 mm
R/H Rear Tyre	165/80 R14	TOYO	8 mm
L/H Rear Tyre	165/80 R14	TOYO	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/07/2023	Inspection Date	18/07/2023
Survey held at	AUTOEXCEL ENGINEERING PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**