	a calka
ASS. REC. BY:	300 7153/kg
From: Date:	Veh No: Type: W.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Estimated Cost:	Type: M.Car / M.Cycle / State of 1969
SO LTP / WS / TP RES / OD RES / EVA / INV / MY	Truck/Trailer & S60 73 C.C.
To Inspect Vehicle No:	D- COM ALEMANIA
at Workshop m/s Alan S	Colour T/Radio: Insuled 1
of	Sp.Reading //0/33 Eng/No: 24.06.597
Policy No.	Eng/No: YV11=540LDG 7406597
Claims No.	Con Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: 600k	Steeding: Inorder / Jammed / Leaked / Burnt
(Client's Record)	Brake: Inorder / Jammed / Leaked J Burnt or
Make of Veh:	Modi: NII / S/RIm / STD A/RIM or
	Tyre Size: F: 235/457R17
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: \$ 53k	Fron! Rear 7
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm UBal.
Est. Repairs: 03 days Res.: Yes or No	D.O.A. 11/7/23 D.O.I. 17/7/2023
Lum Sum: 1.B.1% 3 Val.: Yes or No	Survey held at
	Des. of Damages Frt P Rear I OIS I NIS I UIC I Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to cottision.
Date / Time Action / Instruction	
/ WKSpo rail su 2nd part	Is for this veh.
	the second section of the second section is a second section of the sec
	/
La/Timo, File Pass to? : Prell. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
o/lime, File Return to?	Transportation
Add Fee	Section Section 11 - 2
	Jatandani (C
4 Franciska	
ort Format :	Tech Invs (\$). Others
p Sum / I.B.I: (\$	Weekend (\$
	ICTAL

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550 Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06877

Your Reference : SP2004601407-01 Accident Date : 11-Ju1-2023

Date: 13-Jul-2023

Our Ref : 023146 / CHAN

PAGE: 1

ALLIANZ INSURANCE SINGAPORE PTE LTD

NOT Nothaire

'NA

INA

3

79 ROBINSON ROAD #09-01 Singapore 068897 Menny BY Roing
3 day, Ex & God.

ESTIMATED COST OF REPAIR FOR VOLVO S60 SLA6947G

1	nc	Front grille	2001	Cm 780.00 -
	PC	Tronc Billie	assy	700.00
1	pc	Front grille	air cowling	750.00
1	pc	Front bumper	fascia	750.00 7 1,900.00
1	pc	Front bumper	reinforcement	1,300.00
1	pc	Front bumper	sponge	500.00 7
			side retainer	a se120 00 1 240.00 X
		Front bumper		@ s\$ 7.00 Na 49.00 —
1	pc	N/s headlamp	assy	@ \$\$ 7.00 Ma 49.00
				7.419.00

741.90 Add: 10%:

1 pc Front no.plate with box

nu8,160.90 45/A 50.00 sn

To putty and spray replaced parts

500.00 2501

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

500.00 250

Total:

S\$ 9,210.90 =========

Singapore Dollars Nine Thousand Two Hundred and Ten and Cents Ninety Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
 To display bemaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SC1N237B000H-01 / City Auto Pte Ltd ENTRY DATE & TIME: 11/07/2023 17:16 (SGT) SUBMITTED BY: Jason Quak VERSION: 2 (12/07/2023 10:23 (SGT))



IMPORTANT NOTICE

al

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies.

policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

11/07/2023 17:16 (SGT) **Date of Submission** Both Policyholder and Actual Driver Reported by 11/07/2023 07:19 (SGT) Date of Accident cact Location of Accident Singapore ANG MO KIO AVE 1 Additional Location Information Singapore Country/State of Loss

DETAILS OF OWN VEHICLE

SLA6947G Vehicle Registration Number

INSURED/POLICYHOLDER

Is company? LIM GUANG CHENG ROGER Name Of Registered Owner NRIC No SXXXX273B ROGERGCLIM@GMAIL.COM Email Address (Phone) +65-97667892 Mobile Phone No. Alternative Phone No

VEHICLE PARTICULARS

Volvo S60 Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Private car Vehicle Category Auto Transmission 1969 CC

INSURANCE COMPANY

Name of Insurance Company Allianz Insurance Singapore Pte. Ltd. Policy Number / Cover Note Number SP2004601407-01

DRIVER

LIM GUANG CHENG ROGER Name of Driver SXXXX273B NRIC No 20/12/1984 Date Of Birth Indoor Occupation

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the daims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, maylare permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


CITY AUTO PTE LTD Bik & Sin Ming Road

#01-58/60/82 Sin Ming Ind Est Singapore 575543

Tel: 6453 1235 Fax: 6453 7944 Witnessed by Recording Committees from brinel (Name as in NRIC/ID card)

117/2023 Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder)./ Date & Time



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID:	273B	
Vehicle Details		
Vehicle No.:	SLA6947G	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	17 Jul 2023	
Vehicle Make:	VOLVO	
Vehicle Model:	S60 T5 A/T ABS D/AIRBAG 2WD	
Primary Colour:	Grey	
Manufacturing Year:	2015	
Engine No.:	B4204T111470192	
Chassis No.:	YV1FS40LDG2406597	
Maximum Power Output:	180.0 kW (241 bhp)	
Open Market Value:	\$25,671.00	
Original Registration Date:	11 Mar 2016	
First Registration Date:	11 Mar 2016	
Transfer Count:	0	
Actual ARF Paid:	\$27,940.00	
Intended PARF Rebate Details		
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	10 Mar 2026	
PARF Rebate Amount:	\$16,764.00	
ntended COE Rebate Details		
COE Expiry Date:	10 Mar 2026	oldonio pregganti nitro (no. 1
OE Category:	B - Car above 1600cc or 97kW (130bhp)	
OE Period(Years):	10	
P Paid:	\$47,604.00	
OE Rebate Amount:	\$12,581.00	
otal Rebate Amount:	\$29,345.00	