



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD C/O JUST LAW LLC 101 CECIL STREET #12-12 TONG ENG BUILDINGSINGAPORE 069533			Ref: CS3/CTI22007472/Tvp3e2-1 Date: 31/07/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 7242L	Veh. Inspected	SMP 2740X	
Policy No.	SNM22D205143/C02/tankl/leepg	Coverage (\$)	0.00	
Claim No.	BRR/AL/9857/23	Excess (\$)	0.00	
Assign From	BRIJ RAI/AMBROSE LEE(JUST LAW LLC)	Assign Date	11/07/2023	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GP72007360	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	KAPSEN	6 mm	
L/H Front Tyre	185/60 R15	KAPSEN	6 mm	
R/H Rear Tyre	185/60 R15	KAPSEN	6 mm	
L/H Rear Tyre	185/60 R15	KAPSEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION, O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/07/2022	Inspection Date	05/08/2022	
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			16 Working Days	