

OS 1113 Ref: 2
ASS. REC. BY: 2

REF: CC2/MID 23007175/RP

2006

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: SLV 2021T
at Workshop m/s PEHASWS
of KIAN TUK RD
Insured: MIWDEF
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Est. or Market Value: 59K
IDAC Accident Report: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 33K

Veh No: SLV 2021T Yr Regn: 2017 / DK
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: MAZDA 3 SEDAN 1.5 AT C.C. 1496
Colour: BLACK A/C: Insured / Std / NI / NA
Sp. Reading: 352201 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: 3M 6BN 22A 84 0157986
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/60 R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / WST LAKE / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front R/Bal. 6 mm Rear R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 13/01/23 D.O.I. _____
Survey held at PEHASWS
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
O/S FR
The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

) \$ + RS. \$ _____

☐ : Interview (\$ _____)

) Photos

☐ : Tech. Invs (\$ _____)

) Others

☐ : Weekend (\$ _____)

)

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE 628800

Officer in Charge : VIVIAN TAN EE WI
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
3 MEDIA CLOSE #07-03
SINGAPORE 138498

Attn :
Tel :
Fax No. :

Quotation No. : QO23/07-1117	Quotation Date : 17/07/2023	Terms : 60 DAYS
Vehicle No. : SLV2021T	Chassis No. : JM6BN22A8H0157986	Policy Number : A29069766MKF
Model : MAZDA 3		Date of Accident : 13/07/2023
Third Party Insurer : MINDEX		TP Vehicle No. : 21289MID
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	SIDE MIRROR (RHS) <i>Q15 ✓</i>	1	498.0000	498.00
2	SIDE MIRROR COVER (RHS) <i>repair</i>	1	158.0000	158.00
3	FRONT DOOR (RHS) - REPAIR <i>X</i>	1		
4	FRONT DOOR OUTER CHROME MOULDING (RHS) <i>X</i>	1	198.0000	198.00
5	FRONT DOOR QUATER APPLIQUE (RHS) <i>X</i>	1	125.0000	125.00
6	LESS 20%	1	-195.8000	-195.80
7	TO REARRANGE ELECTRICAL WIRING SYSTEM FOR FACILITATE REPAIR.	1	100.0000	<i>30</i> 100
8	TO KNOCKING & PANEL BEATING.	1	400.0000	<i>100</i> 400
9	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.	1	500.0000	<i>60</i> 500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repairer
HP 900/10068
1 day
P/P
19/07/23
Repair after repair

Sub Total	1,783.20
GST(8.00%)	142.66
Total (SGD)	1,925.86

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	200G
Vehicle No.:	SLV2021T
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jul 2023
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	P520450716
Chassis No.:	JM6BN22A8H0157986
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,937.00
Original Registration Date:	26 Dec 2017
First Registration Date:	26 Dec 2017
Transfer Count:	1
Actual ARF Paid:	\$9,937.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2027
PARF Rebate Amount:	\$6,955.00
COE Expiry Date:	25 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,900.00
COE Rebate Amount:	\$19,005.00
Total Rebate Amount:	\$25,960.00

The information contained herein is correct as at 20 Jul 2023

OK