

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/11123007210/Uny3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: G3H58927at Workshop m/s Auto city

of _____

Insured: SHD25277

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \$66k.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 3

days

Res.: Yes or No

Lum Sum: 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C320C

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: G3H58927Yr Regn: 20/07/18Type: M.Car / M.Cycle / Bus / Van / Car / Taxi / Prime Mover /Truck / Trailer or CarMake: ToyotaDyna

C.C

2982Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 108601

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35Y20K210770Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/75R16 BSR: 155R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Green-Max

Front

Rear

R/Bal. 7 mmR/Bal. 7/7 mmL/Bal. 7 mmL/Bal. 7/7 mmD.O.A. 29/03/23D.O.I. 17/7/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or2/5 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/7/23 4/5 @ 1300 informed AH back (Red, \$2989.28, 69%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	320C
Vehicle Details	
Vehicle No.:	GBH5892T
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jul 2023
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1KD2805175
Chassis No.:	JTFAT35Y20K210770
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	20 Jul 2018
First Registration Date:	20 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jul 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$27,047.00
COE Rebate Amount:	\$13,538.00
Total Rebate Amount:	\$13,538.00

The information contained herein is correct as at 17 Jul 2023

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad


Advertiser Login

Ways of Selling

Volkswagen Sportsvan 1.4A Highline Sunroof.



Very Low Mileage! Direct Owner
Pricing!
Direct Owner StarAd

Sort by 20

14 vehicles



TOYOTA DYNA

Any Category

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	TOYOTA DYNA		Any	Any	2018	Any	Any	Any
	Toyota Dyna	150 3.0M	\$77,800	\$15,550 /yr	17-Jul-2018	2,982 cc	-	Truck
	Fuel Type: Diesel Please call to arrange for viewing thank you. Posted: 17-Jul-2023							
	Toyota Dyna	150 3.0M	\$77,888	\$15,750 /yr	26-Jun-2018	2,982 cc	-	Truck
	Fuel Type: Diesel Excellent engine and gearbox condition. Full canopy with brand new checkered plate. Newly renew road tax with rare G plate Dyna in th... Lek Auto Pte Ltd Posted: 17-Jul-2023							
	Toyota Dyna	150 3.0M	\$85,800	\$16,440 /yr	04-Oct-2018	2,982 cc	-	Truck
	Fuel Type: Diesel Special Promotion! 3% cash rebate on selling price. 8% rebate on Insurance Premium. Top up \$88 to get lifetime servicing. Well maintai... ABS Bus Pte Ltd Posted: 16-Jul-2023							
	Toyota Dyna	150 3.0M	\$78,888	\$16,980 /yr	09-Mar-2018	2,982 cc	-	Truck
	Fuel Type: Diesel 1 owner, low mileage done, lorry maintained well, almost new and clean, wear and tear replaced with new set of 6 tyres. Pioneer high e... Wunder Auto Pte Ltd Posted: 15-Jul-2023							
	TRD Toyota / Nissan Tyre Valve Cap (With Keychain Wrench) Unique and comes with a keychain wrench. More info about this product							
	Toyota Dyna	150 3.0M	\$85,800	\$16,270 /yr	24-Oct-2018	2,982 cc	-	Truck
	Fuel Type: Diesel Special offer with just top up \$88 to get the lifetime servicing. 8% rebate on insurance premium, 3% rebate of selling price. Previously u... ABS Bus Pte Ltd Posted: 14-Jul-2023							

Compare

Auto City Pte Ltd

32 Kaki Bukit Crescent, Singapore 416262

Tel: 6846 8855 (Raymond)

not added
1/5 @ 1300
3 days
17/7/23

Vehicle number: GBH5892T

Vehicle Made & Model: TOYOTA DYNA

Qty List Items

- | | |
|---|-------------------------------|
| 1 | Rear wheel guard assy - RH |
| 1 | Rear wheel hub shaft - RH |
| 1 | Rear wheel bearing |
| 1 | Rear wheel hub shaft oil seal |

	Amount \$
Dis	871.65
11	861.95
11	180.90
11	151.20
Sub-total	2,065.70
Less 25%	516.43
Total List	1,549.28

Special Nett Items

- | | |
|---|-----------------------------------|
| 1 | Rear wheel rim - RH |
| 1 | Rear tyre |
| 1 | Rear side panel lower member - RH |

R	180.00
11	160.00
R	800.00
Total Special Nett	1,140.00

Labour charges

- | | | |
|---|----|--------|
| To remove, refix front undercarriage | 11 | 200.00 |
| To respray painting and etc | | 600.00 |
| Panel beating, cut, weld remove & replacing above parts | | 800.00 |

Total Labour 1,600.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 4,289.28

2- 871.65
252
653.73
980
7633.73
202
1306.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 1

Acknowledged by Repairer

Signature:

Date: