

ASS. REC. BY:

REF:

ICS / 230072371/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

Optima

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

1K

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

887K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SOV 739P

Yr Regn:

101 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

C.C.

1998

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

195061

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

THMFD 2640 AS 200014

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

15/7/23

D.O.I.

18/7/2023

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Modify exhaust pipe, air-filter, oil cooler unit, Bonnet

4/8 11:00 & 4:00 Cncl

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	530B
Vehicle Details	
Vehicle No.:	SDV739P
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jul 2023
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 2.0L 5AT
Primary Colour:	White
Secondary Colour:	Black
Manufacturing Year:	2009
Engine No.:	K20Z25500014
Chassis No.:	JHMF2640AS200014
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$27,773.00
Original Registration Date:	27 Oct 2011
First Registration Date:	27 Oct 2011
Transfer Count:	2
Actual ARF Paid:	\$27,773.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2031
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$58,124.00
COE Rebate Amount:	\$47,677.00
Total Rebate Amount:	\$47,677.00

The information contained herein is correct as at 17 Jul 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/07/2023 12:38 (SGT)
Reported by	Actual Driver
Date of Accident	15/07/2023 14:10 (SGT)
Exact Location of Accident	Changi Rd, Singapore
Additional Location Information	ALONG CHANGI RD APPROACHING JUNCTION OF FRANKEL AVE & JLN KEMBAGAN
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDV739P
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	KAM CHEE PENG
NRIC No	SXXXX530B
Email Address	ARROWFAT@GMAIL.COM
Mobile Phone No	(Phone) +65-97882724
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Civic
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1998

INSURANCE COMPANY

Name of Insurance Company	ECICS Limited
Policy Number / Cover Note Number	MPC22P00251000

DRIVER

Name of Driver	KAM CHEE KEONG, RICHIE
NRIC No	SXXXX956Z
Date Of Birth	26/05/1981

Occupation	Indoor
Date Of Driving Pass	02/01/2009
Driving experience	14 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81632422
Alt. Phone Number	-
Email Address	IMROCK@HOTMAIL.COM
Address	BLK 539 PASIR RIS STREET 51
Address complement	#03-32
Postcode	510539
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Sibling
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA3552D
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-

Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMG5846C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan





Describe Circumstances of the Accident



I was driving along Changi Rd approaching junction of Frankel Ave & JLN Kenangan, upon crossing junction the car in front (SMG 5846L) suddenly came to an abrupt stop immediately after the junction yellow box. I ~~was~~ not able to stop in time and impacted the red car in front. At the same time slightly after I impact the front car, a taxi (SHIA 3552D) hit me from the rear resulting in a chain collision with the SMG 5846L in front, my vehicle (SA 739R) in the middle and the taxi the rear (HIA 3552D).

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

 
Witnessed by Reporting Centre Personnel

Optima Werkz Pte Ltd
 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
 Singapore 568047
 Tel: 6481 1522

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC22P00251000	Date of Loss:	15/07/2023
Vehicle Reg. No.:	SDV739P	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KAM CHEE PENG		
Make/Model:	HONDA CIVIC, 2.0 L (A)	Vehicle Reg. Date:	27/10/2011
Vehicle Colour:	WHITE	Chassis No:	JHMF2640AS200014
Engine No:	K20Z25500014		
Odometer:	195061 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5 ✓		
Present Location:	OPTIMA WERKZ PTE LTD (HQ)		

*Not Authorized
 L1 Pump &
 Reentry After Repair
 Ex @ 1000.*

COST OF CLAIMS

	Amount
Parts	4,885.10
Miscellaneous Items	230.00
Labour	1,800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,915.10
+ GST 8.00% (S\$)	553.21
Nett Amount (S\$)	7,468.31

This claim is handled by: LING TING ANGenerated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Jul 2023)
Parts: 143 HONDA CIVIC 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDV739P)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		Air-cond condenser	0.00	0.00	R3 *415.00 F	✓
2	1		Bonnet	0.00	0.00	Rn *330.00 F	X
3	1		Bonnet hinge LH	0.00	0.00	R1 *35.00 F	X
4	1		Bonnet hinge RH	0.00	0.00	R1 *35.00 F	X
5	1		Bonnet lock	0.00	0.00	R1 *70.00 F	✓
6	1		Bumper bracket LH, front	0.00	0.00	D11 *18.00 F	✓
7	1		Bumper bracket RH, front	0.00	0.00	Rn *18.00 F	X
8	1		Bumper reinforcement, front	0.00	0.00	R1 *200.00 F	✓
9	1		Bumper, front	0.00	0.00	CM *220.00 F	✓
10	1		Headlamp LH	0.00	0.00	MJCM *460.00 F	✓
11	1		Headlamp RH	0.00	0.00	LT *460.00 F	✓
12	1		Panel, front	0.00	0.00	R1 *780.00 F	✓
13	1		Radiator	0.00	0.00	Rn *350.00 F	X
14	2		Radiator fan blade	0.00	0.00	CM *140.00 F	✓
15	1		Radiator fan guard	0.00	0.00	CM *100.00 F	✓
16	2		Radiator fan motor	0.00	0.00	Tm *280.00 F	✓
17	1		Radiator grille	0.00	0.00	CM *370.00 F	✓
18	1		Radiator grille emblem	0.00	0.00	CM *20.00 F	✓
19	1		*SUPPORT PANEL TOP GARNISH	0.00	0.00	Sn *60.00 F	X
20	1		*FRONT GRILLE OUTER GARNISH COVER	0.00	0.00	CM *80.00 F	✓

F=Franchise part.

Sub Total (S\$) 4,441.00
+ Margin on L,N Items 10.00% (S\$) 444.10
Total Parts (S\$) 4,885.10

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRONT BUMPER CLIPS
2	1	FRONT GRILLE CLIPS
3	1	FRONT NUMBER PLATE & HOLDER
4	1	RADIATOR COOLANT

nd *na* 50.00 —
na 50.00 —
45/na 50.00
na 80.00 *60/na*

Sub Total (S\$) 230.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST FRONT ACCIDENT AREAS & ETC.	New	800.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH & ETC.	New	800.00
3	TO REFILL AIRCON GAS & ETC.	New	80.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM.	New	120.00

600/
600/
✓
20/

Gross Labour Cost (S\$) 1,800.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >