



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883 ON BEHALF OF HOON MING HUI			Ref: CS/TP23007249/Uvy3m4 Date: 31/07/2023 Code: TP149	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SME 4584A	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	19/07/2023	
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	RU11301662	Colour	WHITE
	Odometer	81472 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	MICHELIN	7 mm
	L/H Front Tyre	215/60 R16	MICHELIN	7 mm
	R/H Rear Tyre	215/60 R16	MICHELIN	7 mm
	L/H Rear Tyre	215/60 R16	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/07/2023	Inspection Date	19/07/2023
	Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	