

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JSE 9098

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: RM 40k.

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

JSE 9098

Yr Regn:

108

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Toyota Mark X 2500 2499

Colour:

pearl white

A/C:

Insured / Std / NI / NA

Sp. Reading

288797

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

62X1203061249

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/45ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Grip max

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18/7/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)



SINGAPORE POLICE FORCE



T/20230716/2055

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

1 of 3

Report No. T/20230716/2055

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/07/2023 17:42		Vide Report No.: E/20230716/0110		Station Diary No.: 55
Informant's Particulars				
Name of Informant: CHEN JUN KET		Address: 698 HOUGANG STREET 61 #03-16 HOUGANG SPRING SINGAPORE 530698		
ID Type / ID No.: FIN NO / G6887987L		Contact No.: Home/Office: Mobile: 94999902		
Nationality: MALAYSIAN		Email: jschen6008@gmail.com		
Sex: Male	Age: 31	Date of Birth: 14/02/1992	Type of Informant: Driver	
Race: Chinese		Language:		
Occupation: TECHNICAL INSTALLER		Driving Licence Information: Class: Date of Expiry:		


General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 16/07/2023 16:00	Type of Location: Expressway
Location: PAN-ISLAND EXPRESSWAY				
Lamp Post Number: 1125				
Weather: Clear		Road Surface: Dry		
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JSE9098	Car				Slightly Damaged	1
SKK9936C	Car				Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20230716/2055

2 of 3

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

Report No. T/20230716/2055

CONTINUATION OF REPORT

Driver			
Name	CHEN JUN KET	ID No.	G6887987L
Related Vehicle	JSE9098 (Car)	Contact No.	94999902
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	LIM SHIN HUEY	ID No.	T0277220A
Related Vehicle	SKK9936C (Car)	Contact No.	91889070
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 16/07/2023 at about 3.35pm, I was driving from Toa Payoh on the PIE with my friend. We were going to West Coast to eat. Along PIE pass the 22.5km mark, I saw there was tree pruning on the rightmost lane of PIE. I then changed lane to lane 2. The car in front of me stopped, as such I also slowed down and stopped. I inched out my car slightly as I wanted to change lane to lane 3, however I felt an impact at the back of my car.

I alighted from my car and checked the damages. The rear bumper was dented and scratched, and both the rear lights were broken as well. We exchanged our particulars and contact details. As we shifted our cars to lane 1, traffic police arrived to the scene. I was given a case card (E/20230716/0110) and advised to lodge a traffic accident report. I downloaded the in-car camera footages on my phone and sent them to the traffic police IO (Ila, tel: 6547 6187).

I was feeling a bit of shock and giddiness after the impact, but I am feeling fine now. I also have some redness on my right shoulder caused by my seatbelt due to the impact. My passenger seated at the front passenger seat was not injured. I will visit a doctor if I'm feeling discomfort or pain.



**SINGAPORE
POLICE FORCE**



T/20230716/2055

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

3 of 3

Report No. T/20230716/2055

CONTINUATION OF REPORT

Signature of Officer Recording The Report:

E /

SGT 3 RACHEL ZHUANG
QINGXIN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

SR STAFF SGT SYED MUHAMMAD ISA BIN
OMAR ALHABSHEE

Contact No.: 65476187

Signature Of Informant:

Date/Time:

16/07/2023 17:42

Classification Of Case:

NP168