

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	LOTION IXE	Ref:	CS3/SMO23007272/Kqp3e2		
	50 RAFFLES PLAC		Date:	21/07/2023		
		TOWERSINGAPORE 048623		Date.	21/01/2020	
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SFV 8800T	Veh. Inspected	ı	SLZ 6936G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2302815/THE	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		18/07/2023	
2.	Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	RU11230657	Colour		METALLIC RED	
	Odometer	116550 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	SAILUN		9 mm	
	L/H Front Tyre	215/60 R16	SAILUN		9 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP		3 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP		3 mm	
4.	Description of Damages					
	THE VEHICLE SUS	VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
5.	. General Information					
	Accident Date	17/07/2023	Inspect Date /	Time	19/07/2023 (11:35 AM)	
	Survey held at GRANDE AUTO CREDIT PTE LTD					
	60 JALAN LAM HUAT, #05-37/38, CARROS CENTRE, SINGAPORE 737869					
5a.	ia. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					

Report Ref No. CS3/SMO23007272/Kqp3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser