

ASS. REC. BY: Kenneth REF: LPCI 23 006012/KVY3-1

ASSIGNMENT

From: _____ Date: _____ Estimated Cost: _____ OD/TP/WS/TP RES/OD RES/EVA/INV/MY To inspect Vehicle No: _____ at Workshop m/s <u>Wah Yu</u> <u>2941</u> of <u>176 05-09</u> Insured: <u>GR 663J</u> Policy No. _____ Claims No. <u>22/23/23/VC05/027546</u> Sum Insured: _____ Excess: _____ (Client's Record) Make of Veh: _____ (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: <u>\$94k</u> IDAC Accident Report: _____ Consistent?: Yes or No GIA / PR Seen: _____ Consistent?: Yes or No Est. Repairs: <u>12-14</u> days Res.: Yes or No um Sum: <u>20</u> % 3 Val.: Yes or No A / REV / REP. / 24 HRS Vehicle: IN / OUT Person Contacted: _____	Veh No: <u>SMC5849R</u> Regn: <u>07, 18</u> Type: <u>M/Car</u> M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: <u>Honda Civic</u> c.c. <u>1498</u> Colour: <u>M-L Grey</u> A/C: Insured / Std / NI / NA Sp. Reading: <u>119619</u> T/Radio: Insured / Std / NI / NA Eng/No: _____ C/No: <u>MR1HFC1660 JT000089</u> Gen. Cond: <u>Good</u> / Fair / Poor / Burnt Steering: In order / Jammed / Leaked / Burnt or Brake: In order / Jammed / Leaked / Burnt or Mod: <u>NI</u> / <u>2Rim</u> / STD A/Rim or Tyre Size: F: _____ R: <u>235/45ZR17</u> BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or <u>Tourado</u> <table border="0" style="width: 100%;"> <tr> <td style="width: 50%;"> Front R/Bal. <u>8</u> mm L/Bal. <u>8</u> mm D.O.A. <u>12/6/23</u> </td> <td style="width: 50%;"> Rear R/Bal. <u>8</u> mm L/Bal. <u>8</u> mm D.O.A. <u>14/6/2023</u> </td> </tr> </table> Survey held at _____ Des. of Damages: Frt / <u>Rear</u> / O/S / N/S / UIC / Rooftop or The UIC / Chassis frame / Body Structure affected due to collision.	Front R/Bal. <u>8</u> mm L/Bal. <u>8</u> mm D.O.A. <u>12/6/23</u>	Rear R/Bal. <u>8</u> mm L/Bal. <u>8</u> mm D.O.A. <u>14/6/2023</u>
Front R/Bal. <u>8</u> mm L/Bal. <u>8</u> mm D.O.A. <u>12/6/23</u>	Rear R/Bal. <u>8</u> mm L/Bal. <u>8</u> mm D.O.A. <u>14/6/2023</u>		

Date / Time	Action / Instruction
1	PRS, no documents given, Bootlid jammed
24	Repair cost \$10-12k
21/7/23	Submit LS \$14,700 (red 4500, 23%)

no, File Pass to? ☐ : Prell. Report

no, File Return to? ☐ : Final Report

21/7/23-typist

Format: _____

Sum / I.B.I: (\$ _____)

Days Of Repair: 14

Resurvey No. of Trip: _____

Survey Fee: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech Invs (\$ _____)

☐ : Weekend (\$ _____)

Transportation: _____

Food: _____

Others: _____

TOTAL: _____