

(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/INC23007310 / U

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC9003C

at Workshop m/s 3m 10am

of _____

Insured: FB7354

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$100k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C7786
Vehicle: IN / OUT

Date: _____ Person Contacted: 27A 18366

Veh No: PC9003C Yr Regn: 10/11/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: VOLVO B7R C.C. 7146

Colour: multi colour A/C: Insured / Std / NI / NA

Sp. Reading: 317983 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YV3R6R624HA185-776

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295 / 80 R 22.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6/6 mm

R/Bal. 6 mm R/Bal. 6/6 mm

L/Bal. 6 mm L/Bal. 6/6 mm

D.O.A. 15/07/23 D.O.I. 28/07/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Dep 24k.
	have video of folder + 9 seater
	501 4 yrs. 3 months plus

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

_____ S + RS. SI

Photos

Others

Report Format : _____

Lump Sum / I.B.I: (\$)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	778G
Vehicle Details	
Vehicle No.:	PC9003C
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jul 2023
Vehicle Make:	VOLVO
Vehicle Model:	B7R AUTO
Primary Colour:	Multicolor
Manufacturing Year:	2017
Engine No.:	D7E12017245
Chassis No.:	YV3R6R624HA185776
Maximum Power Output:	-
Open Market Value:	\$138,133.00
Original Registration Date:	10 Nov 2017
First Registration Date:	10 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$6,907.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Nov 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$18,366.00
Total Rebate Amount:	\$18,366.00

The information contained herein is correct as at 25 Jul 2023

OK