

(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/INC23007310/Uny3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC9003C

at Workshop m/s 3m 10am

of _____

Insured: FBP7354

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$100k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 7786
Vehicle: IN / OUT

Date: _____ Person Contacted: 27A 18366

Date / Time _____ Action / Instruction Dep 24k.

have video of folder 49 seater

3rd 4 yrs. 3mth plus

4/5 @ 4500 informant Kenny (Red. \$ 6363, 58%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ _____)

Veh No: PC9003C Yr Regn: 10/11/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: VOLVO B7R c.c 7146

Colour: multi colour A/C: Insured / Std / NI / NA

Sp. Reading: 317983 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YV3R6R624HA185-776

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/80R22.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6/6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

15/07/23

D.O.I.

28/07/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 2/5

The U/C / Chassis frame / Body Structure affected due to collision.

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	778G
Vehicle Details	
Vehicle No.:	PC9003C
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jul 2023
Vehicle Make:	VOLVO
Vehicle Model:	B7R AUTO
Primary Colour:	Multicolor
Manufacturing Year:	2017
Engine No.:	D7E12017245
Chassis No.:	YV3R6R624HA185776
Maximum Power Output:	-
Open Market Value:	\$138,133.00
Original Registration Date:	10 Nov 2017
First Registration Date:	10 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$6,907.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Nov 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$18,366.00
Total Rebate Amount:	\$18,366.00

The information contained herein is correct as at 25 Jul 2023

OK

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

VEHICLE No: PC 9003C

NETT ITEM

1PC	REAR BUMPER WITH BRACKET	R		\$2,625.00	X
1PC	REAR BUMPER DOME O/S	Cne	3000	\$3,800.00	
1SET	REAR BUMPER REVERSE SENSOR	n1		\$250.00	X
1PC	REAR EXHAUST	5enf/1m	1620	\$1,815.00	
1PC	REAR EXHAUST BRACKET	SCC		\$180.00	X
				\$8,670.00	
			LESS 10%	\$7,803.00	

TO CHECK WIRING

11 \$80.00 X

TO DISMANTLE & REFIX REAR REVERSE SENSOR

\$80.00 40

TO DISMANTLE & REPLACED REAR EXHAUST

\$200.00 80

LABOUR FOR PANEL BEATING & REPLACED PARTS

\$1,200.00 600

TO PUTTY & SPRAY PAINTING

\$1,500.00 680

TOTAL \$10,863.00

not Auth'd
llm
moray
28/7/23

2/5 @ 4500
2 days

P- 4720
102
4848
1400
5248
202
4518

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: