

(08/11/13) wef

ASS. REC. BY:

Pasul

REF:

CS/A1523007319/Rnp3

2412

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDH 8282K

at Workshop m/s

PERFORMANCE

of

ALEXANDER ON

Insured:

A15

Policy No.

Claims No.

Sum Insured:

Excess:

600


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

105K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA (REV) / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 19K

Veh No:

SDH 8282K

Yr Regn: 2015 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B-M-W 740LI SR

c.c 2998

Colour

GREEN

A/C: Insured / Std / NI / NA

Sp. Reading

156986

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA 7E220304522764

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R20

R:

21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

15/07/23

D.O.I.

19/07/23

Survey held at

PERFORMANCE

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) S + RS SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Car In

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 66726
Date Estimated : 18/07/2023
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lee Ke Hoo
28 Springleaf Garden

Singapore 788188

- ACCOUNT - 224093

Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDH8282K	WBA7E22030G522764	26/11/2015	740Li	112448

DESCRIPTION

VALUE

To replace front bumper, bonnet, front wall and attachments.

3400 5,180.00

To painting front bumper and bonnet.

2219 2,336.00

To check electrical wiring system at the front section
for proper function including adjustment of headlights.

1683 171.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

168 177.00

To replace right headlight.

457? 481.00

To replace left headlight.

457? 481.00

To replace radiator assembly, fan housing with fan including
pressure test, bleed cooling system and conduct check for
leak. (For 7 series only).

896? 944.00

To remove and install front view
camera including program and conduct check for proper
function.

252 266.00

To carry out body cavity preservation.
(Per panel).

112 118.00

Sundries.

? 150.00

Total Labour 1: 10,230.00

DESCRIPTION

QTY

PRIC

VALUE

RADIATOR

1

1,163.15

1,163.15

ALUMINIUM BONNET

1

3,388.95

3,388.95

LH SUPPORT FOG LAMP

1

103.80

103.80

RH SUPPORT FOG LAMP

1

103.80

103.80

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 66726
Date Estimated : 18/07/2023
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDH8282K	WBA7E22030G522764	26/11/2015	740Li	112448

DESCRIPTION	QTY	PRIC	VALUE
IMPACT ABSORBER TOP <i>cm</i>	1	95.70	95.70
FRT BUMPER CARRIER <i>cm</i>	1	925.30	925.30
FRT BUMPER PANEL PRIMED (PDC/PMA) <i>cm</i>	1	1,768.45	1,768.45
TRIM GRILLE I-CAM <i>sun</i>	1	37.30	37.30
FRT LH GRILLE (PURE EXCELLENCE) <i>cm</i>	1	228.00	228.00
FRT RH GRILLE (PURE EXCELLENCE) <i>cm</i>	1	228.00	228.00
AIR FLAPS TOP <i>cm</i>	1	398.15	398.15
EMBLEM GROMMET <i>m</i>	2	0.95	1.90
BMW EMBLEM 82MM <i>m</i>	1	74.35	74.35
FRT CROSSLINK ?	1	227.20	227.20
CONNECTION FRT TOP ?	1	227.20	227.20
FRT PANEL SUPPORT ?	1	71.25	71.25
AIR DUCT RADIATOR TOP ?	1	83.25	83.25
LH HEADLIGHT LED AHL HIGH (ICON LIG ?	1	6,277.20	6,277.20
RH HEADLIGHT LED AHL HIGH (ICON LIG ?	1	6,277.20	6,277.20

Total Parts : 21,680.15

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 19/07/23 Excess S\$ 600

Surveyor's Name _____ Sign _____

Surveyor's Tel 96010068 Authorised Yes ☒ No ☐

Authorised Date _____ Time _____

REPAIR PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's Email _____

No. of Working Days Recommended 6 days

Resy 54 pmt

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Labour 1	:	10,230.00
Parts	:	21,680.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	2,552.81
Grand Total	:	34,462.96

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	941Z
Vehicle No.:	SDH8282K
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jul 2023
Vehicle Make:	B.M.W.
Vehicle Model:	740LI SR LED NAV HUD
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	20279400B58B30A
Chassis No.:	WBA7E22030G522764
Maximum Power Output:	240.0 kW (321 bhp)
Open Market Value:	\$82,300.00
Original Registration Date:	26 Nov 2015
First Registration Date:	26 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$120,140.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2025
PARF Rebate Amount:	\$72,084.00
COE Expiry Date:	25 Nov 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,501.00
COE Rebate Amount:	\$13,496.00
Total Rebate Amount:	\$85,580.00

The information contained herein is correct as at 20 Jul 2023

OK

BMW 7 Series 740Li Sunroof

\$92,800 Instalment \$3,409/mth

 Car comes with 6-mth [Sgcarmart Warranty](#)

 [Apply for 2.28% loan](#)

 [Shortlist](#)

 [Loan Calculator](#)

**KRABI
AWAITS!**



One-way from
\$

Book now

* Taxes included. Terms apply.



Overview

Financial

Photo

Research

Depreciation	 \$23,960 / year
Reg. Date	10-Apr-2015 (1yr 8mths 20days COE left)
Manufactured	 2014
Mileage	111,000 km (13.4k / year)
Transmission	Auto
Engine Cap	2,979 cc
Road Tax	 \$2,362 / year
Power	235.0 kW (315 bhp)
Curb Weight	 1,845 kg
COE	 \$76,612
OMV	 \$72,784
ARF	 \$103,012
Dereg Value	 \$69,859 as of today

No. of Owners  2