SA1J23530003-02 / ASM Automotive Services Pte Ltd ENTRY DATE & TIME: 03/05/2023 14:32 (SGT) SUBMITTED BY: Nicole Ng VERSION: 3 (04/05/2023 18:10 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving

- and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT	STATEMENT
Date of Submission Reported by Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss	03/05/2023 14:32 (SGT) Owner 30/04/2023 11:30 (SGT) Singapore Along Clementi Avenue 6 towards 10 Buroh Street Singapore
DETAILS OF	OWN VEHICLE
Vehicle Registration Number	XD4695M
INSURED/POLICYHOLDER	
Is company? Name Of Registered Owner Company Reg No Email Address Mobile Phone No Alternative Phone No	Yes TEO BAK SOAH TRADING CO
VEHICLE PARTICULARS	
Manufacturer Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC	Hino Fs1elkd No - Claiming third party Commercial vehicle Manual 12913
INSURANCE COMPANY	

Name of Insurance Company Liberty Insurance Pte Ltd Policy Number / Cover Note Number SD22V10037/VCH/R03

DRIVER

Name of Driver Zhang Zhiyuan NRIC No Date Of Birth Occupation Outdoor

Date Of Driving Pass	
Driving experience	
Gender	Male
Mobile Number	
Alt. Phone Number	-
Email Address	
Address	
Address complement	-
Postcode	542463
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by Driver	- -
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Collision - Head on collision
Weather Conditions	Collision - Head on collision Clear
Road Surface	Dry
noad ounace	ыу
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s)	v
soliciting/offering accident claims assistance?	No
Translator's name	Ng Voon Yee
Translator's ID	TXXXX410B
Translator's phone number	(Phone) +65-62650026
Translator's email	nicoleng@asmauto.com.sg
Original language used in the statement	Mandarin
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	
If yes, against whom?	
CIRCUMSTANCES OF ACCIDENT	
Refer to attached sketch plan.	
ATTACHMENT(S)	
Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
DETAILS OF OTHER	VEHICLE PROPERTY 1
Vehicle Registration Number	ODD0407M

Vehicle Registration NumberGBB2407MVehicle Manufacturer-Vehicle Model-Vehicle Variant-Vehicle Colour-Vehicle CategoryCommercial vehicleName of DriverUddin JaharPassport No/FINGXXXXX306X

Contact Number	
Address	
Address complement	<u>-</u>
Postcode	-
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknow ledge, agree and consent that

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Marin

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



escribe Circumstances of the Accident
I, Zhang Zhi Yuan , the manager of Teo Bak Soah Trading to came to make accident report on behalf of my
co came to make accident report on behalf of my
company. On 3014123 around 11:30 hours, Yishun towing company's staff MV Tao helped us to tow our breakdown truck XD4698M along Clementi Avenue b towards 10 Buroh street on lane 3. As the traffic light turned red, the towing truck then stopped. Out of sudden, there was a lorry GBB2407M came from behind and bang into our
on 30/4/23 around 11=30 hours,
· Yishun towing company's staff My Tao helped us to tow
our breakdown truck XD4695M glong Clementi
Avenue 6 towards 10 Burch street on lane 3. As
the traffic light turned red, the towing truck then
stopped. Out of sudden there was a lorry
GRRZ407M came from behind and base into our
breakdown truck xp4695mfront side.
DICOLD ON K INNE VALORIAN SING.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel






































GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18 00 Singapore 048580 Tel (65) 6224 0010 — Lax (65) 6224 0030 Operating Hours - Monday to Friday, 09:00 — 17:00 UTN: \$6650020G / GST Rep. No.: M400017736

IMPORTANT NOTE: Please submit the completed Addendum form to the <u>same</u> Authorised Reporting Centre with whom you submitted the Original Report.

		ADDEND	MU	
A)	PARTICULARS OF	PERSON MAKING THE AMENDMEN	TS:	
	Original Report No	: SA1J23530003-01	Vehicle Registration No:	XD4695M
	Name(as skownin NR	ICI: TEO BAK SOAH TRADING CO	NRIC/FIN/PassportNo :	
	(*Vehicle Driver/	Vehicle Owner) (*) Please delete as a	appropriate	
	Address			Singapore (659533)
	Contact (Tel)		Mobile No.:_	
	Email Address	1		
	Date of Accident	: 30/4/2023	Time of Accident: 11:30) hours
	Place of Accident	: Along Clementi Avenue 6 t	owards 10 Buroh Street	
		ny: Liberty Insurance Pte Ltd		
	To reattach skete	ch plan		
	Thurs John	i your		
	Policyholder / Driv Date: 04/05/2023		Reporting Centre Pers Name: NRIC/FINNo.:	onnel's Signature

Date:





Liberty Insurance Pte Ltd

Hagatration no 1990; 51 Otub Street #03-00 Liberty House Singapore 069428 Tel. (65) 6221-8611 Websiter retp://www.libertymsurance.com.ag

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1967 FOAD TRANSPORT ACT, 1987 FOAD TRANSPORT (AMENDMENT) ACT 2019 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1969

Certificate No	SD22V10037 /VCH /R03	
Form	MZ301A	
Date Of Issue	27-JUL-2022	
1.Index Mark and Registration No. of Vehicle:	XD4695M	
2.Chassis number of Vehicle:	JHDF\$1ELKXXX10243	
3.Name of Policyholder:	TEO BAK SOAH TRADING CO	
4.Effective date of Commencement of Insurance for the purposes of the Act:	02-AUG-2022 00:00 AM	
5.Date of Expiry of Insurance:	01-AUG-2023 23:59 PM	
6.Persons or Classes of Persons		

entitled to drive":

A) Whilst the vehicle is being used in connection with the Policyholder's business Any person provided he is in the Policyholder's employ and is driving on their order or with their permission.
 B) Whilst the vehicle is being used for social, domestic and pleasure purposes -

Any person who is driving on the Policyholder's order or with their permission,

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or requiation in that behalf from driving. the Motor Vehicle:

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

7.Limitations as to use:

A) Use in connection with the Policyholder's business.

B) Use for the carriage of passengers (other than for hire or reward) in connection with the Policytroidor's pusiness.
 C) Use for social, domestic and pleasure purposes.

8. The Policy does not cover:

A) Use for racing, page-making, reliability trials or speed-testing.

B) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

C) Use for the carriage of passengers for hire or reward.

"Limitations rendered inoperative by Section 6 of the Motor Vehicles | Third Party Fisks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 are not to be included under these headings.

I/We hareby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehiclas (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1967.

> For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers

Authorised Signature

For Information only:

COVERAGE:

Comprehensive, Unlimited Windscreen Third Party Working Risk, Additional Accessories

SUM INSURED: MARKET VALUE AT THE TIME OF LOS

EXCESS: Section

Drivers

FINANCE COMPANY:

DBS BA

PRODUCER NAME: TAN INSURANCE BROKERS PTE LTD

PLSL/-/27/07/2022

S1_CI_T1_T3_OE_Template2-Ver1

27/07/2022

Jul 27, 9022, 19701 PM



10 Buroh Street #04-26/28/29 West Connect building Singapore 627564 Hp: 93809381

Email.: redantsengpl@yahoo.com CO REG NO: 202133953D

REPAIR BILL

XD4695M Hino H700

For Cost of Repairs as recommended by surveyor \$21,693.84 (With GST)

SINGAPORE DOLLARS TWENTY ONE THOUSANDS SIX HUNDREDS NINTY THREE AND CENTS EIGHTY FOUR ONLY

Signature

Company Stamp



6 tampines st 73, #01-03, singapore 528825

tel: 6746 2118 fax: 6746 1148

reg no: 53058468m

To: Teo Bak Soah Trading Co c/o 10 Buroh Street #04-26/28/29,

> West Connect Building, Singapore 627564

Claim Reference : Insured Vehicle No. : Thirty Party Veh No. : Officer-In-Charge : -

Our Reference : KAAS/TA/6575/4695/TP/05.23

Invoice No. : 6575

Date : 15 June 2023

<u>INVOICE</u>				
PARTICULARS	AMOUNT			
Vehicle No. : XD 4695M Make/Model : Hino FS1ELKD ✓ Inspection of Vehicle ✓ Appraisal Report				
 ✓ 100 Colored Photographs ✓ Transport charges ✓ Re-inspection 	SGD 945.00			
Others (Specify)	SGD 945.00			

Dollars: Nine Hundred and Forty-Five Only

(Cheque should be crossed and make payable to " Kelvin Automotive Appraising Services ")



Kelvin Automotive Appraising Services



6 tampines st 73, #01-03, singapore 528825

tel: 6746 2118 fax: 6746 1148

reg no: 53058468m

To: Teo Bak Soah Trading Co c/o 10 Buroh Street #04-26/28/29,

> West Connect Building, Singapore 627564

Claim Reference : Insured Vehicle No. : Thirty Party Veh No. : Officer-In-Charge : -

Our Reference : KAAS/TA/6575/4695/TP/05.23

Date : 15 June 2023

VEHICLE APPRAISAL REPORT

Name of Workshop : Redants Engineering Pte Ltd

Place of inspection : 10 Buroh Street #04-26/28/29, West Connect Building, Singapore 627564

Date of Assignment : 02 May 2023

Date of Accident : 01 May 2023

Date of Inspection : 02 May 2023

PARTICULARS OF INSPECTED VEHICLE

Registration No. : XD 4695M Chassis Frame No. : JHDFS1ELKXXX10243

Make / Model : Hino FS1ELKD Engine No. (Logcard) : E13CUN13076
Year of Manufacture/Reg : 2011 Odometer Reading : 793,933 KM

Colour : Blue Class / Type : Truck

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition : Good
Paintwork : Good
Market Value : Scrap Value : -

CONDITION OF TYRES ON VEHICLE

		Make/Size	Thread Balance
Front	L	BRIDGESTONE 295 / 80 R 22.5	18 mm
Front	R	BRIDGESTONE 295 / 80 R 22.5	18 mm
Rear	L	DURATURN 295 / 80 R 22.5	18 mm
Rear	R	DURATURN 295 / 80 R 22.5	18 mm

^{*}The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.

Our Reference : KAAS/TA/6575/4695/TP/05.23

Vehicle Number : XD 4695M

6 tampines st 73, #01-03, singapore 528825 tel: 6746 2118 fax: 6746 1148

reg no: 53058468m

APPRAISEMENT SCHEDULE

S/N	Qty	y Descriptions	Conditions	Repairer's Estimate		Revised Amount	
		LIST ITEMS:-					
1	1 pc	front bumper	deformed	\$	1,957.28	\$	1,957.28
2	1 pc	front bumper reinforcement	buckled	\$	1,083.33	\$	1,083.3
3	1 pc	front bumper I/h garnish	cracked	\$	90.00	\$	90.0
4	1 pc	front bumper r/h garnish	cracked	\$	90.00	\$	90.0
5	1 pc	front bumper ctr garnish	broken	\$	120.00	\$	120.0
6	1 pc	front bumper I/h corner	missing	\$	145.62	\$	145.6
7	1 pc	front bumper r/h corner	missing	\$	145.62	\$	145.6
8	1 pc	front panel	buckled	\$	2,058.00	\$	2,058.0
9	1 pc	front upper grille	broken	\$	770.49	\$	770.4
10	1 pc	front lower grille	broken	\$	290.00	\$	290.0
11	1 pc	I/h headlamp	broken	\$	290.00	\$	290.0
12	1 pc	r/h headlamp	broken	\$	290.00	\$	290.0
13	1 pc	front I/h signal lamp	broken	\$	135.85	\$	135.8
14	1 pc	front r/h signal lamp	broken	\$	135.85	\$	135.8
15	1 pc	inter-cooler assy	buckled	\$	8,254.76	\$	8,254.7
16	1 pc	inter-cooler r/h hose	damaged	\$	533.30	\$	533.3
17	1 pc	I/h side mirror (B)	damaged	\$	40.00	\$	40.0
18	1 pc	I/h side mirror (M)	damaged	\$	32.00	\$	32.0
19	1 pc	I/h mirror arm	unconfirmed	\$	121.00	177	not affected
20	1 pc	I/h lower panel stand	broken	\$	290.00	\$	290.0
		3.25.		\$	16,873.10	\$	16,752.1
		Less 10%				\$	1,675.2
				\$	16,873.10	\$	15,076.8
		SPECIAL NETT ITEMS:-		Ь			
21	1 pc	front no. plate	buckled	\$	60.00	\$	50.00
22	1 pc	advertisement sticker (company)	necessary	\$	200.00	\$	180.0
				\$	260.00	\$	230.0
			Sub - Total	\$	17,133.10	\$	15,306.8

Our Reference : KAAS/TA/6575/4695/TP/05.23

Vehicle Number : XD 4695M

6 tampines st 73, #01-03, singapore 528825 tel: 6746 2118 fax: 6746 1148

reg no: 53058468m

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
	Ī	B/F LABOUR & OTHER CHARGES:-		\$ 17,133.10	\$ 15,306.8
1		To panel beating ,remove and replace all damaged parts. Dismantle and assemble of radiator assy, aircon pipes and air hose assy to change inter-cooler.		\$ 3,800.00	\$ 3,200.0
2		To check wiring and rewire		\$ 120.00	\$ 100.0
3		Coolant water 20 litres		\$ 120.00	\$ 80.0
4		Vacuum and refill gas R134a		\$ 150.00	\$ 120.0
5		To apply anti-rust		\$ 100.00	\$ 80.0
6		To putty and spray-paint of affected areas		\$ 1,600.00	\$ 1,200.0
			Sub - Total	\$ 23,023.10	\$ 20,086.89



6 tampines st 73, #01-03, singapore 528825

tel: 6746 2118 fax: 6746 1148


reg no: 53058468m

Our Reference

Vehicle Number

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and

the impact was delivered





ASSESSMENT SUMMARY

portion of the vehicle.

: KAAS/TA/6575/4695/TP/05.23

: XD 4695M







The general area of damages is at the

(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs

Redants Engineering Pte Ltd

23,023.10 .

We have adjusted the cost to

20,086.89 and the repairer has agreed to undertake the repairs at a

Part by Part Basis of

\$ 20,086.89 to a acceptable quality and standards.

However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of

10

working days.

100 photographs were taken at the time of static inspection.

This report is strictly done in a Without Prejudice Basis.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No.

6575

for our services rendered and

we thank you for engaging our services.

KELVIN AUTOMOTIVE APPRAISING SERVICES



KELVIN TEO

Licensed Automotive Appraiser Nitec in Automotive Technology Cert. Crash Investigation & Reconstruction Dip MS

MSAAA, AM SAE-A

NOTE: This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.

















































































































































































Your Ref : GBB 2407M Fax : 6538 3708

Our Ref : $JP/DS/22/XD \ 4695M/RED$ Tel : 3152 0985

Date : 3 May 20243 Email : jiapei@kscgp.com

LONPAC INSURANCE BHD

BY EMAIL ONLY

DATE OF ACCIDENT: 1 MAY 2023 NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We are instructed by the owner of XD 4695M to notify you of a road traffic accident on 1 May 2023 at 11.30am along Clementi Avenue 6 towards 10 Buroh Street, involving our client's vehicle registration number XD 4695M and vehicle registration number GBB 2407M which was insured by you at the material time. A copy of the Singapore accident statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

NB. Any settlement or offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude client's driver/passenger from claiming injury-related damages arising from this accident.

Yours	faithful	lly,
-------	----------	------

Ds

Enc.

Your Ref : GBB 2407M Fax : 6538 3708
Our Ref : JP/DS/23/XD 4695M/RED Tel : 3152 0985

Date : 4 May 2023 Email : jiapei@kscgp.com

LONPAC INSURANCE BHD.

BY EMAIL ONLY

DATE OF ACCIDENT: 1 MAY 2023 NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/no.	Surveyor
1.	Kelvin Teo from Kelvin Automotive Appraising Services
2.	Ho Joo Loong, Danny

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : RedAnts Engineering Pte Ltd

10 Buroh Street

#04-26/29 West Connect Building

Singapore 627564

Contact Person/Tel : Michael Kwek /Mb: 9380 9381

Yours faithfully,

Ds



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

9 Temasek Boulevard, Suntec City Tower Two #42-01B Singapore 038989

 $\hbox{E-mail: gears-support@shift-technology.com}\\$

GST Registration: M400017735

TAX INVOICE

Date of Request: 11/07/2023

Your Ref No: JP/DS/23/2886/RED

Dear Sir/Madam,

Date of Accident: 30/04/2023 12:03 (SGT)

Vehicle No: XD4695M

Place of Accident: Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
GBB2407M	Singapore	(31.00)	1	(28.70)
GST Amount			(2.30)	
Total Amount Due (GST Inclusive)		(31.00)		

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving

- and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 03/05/2023 14:36 (SGT) Reported by **Actual Driver** Date of Accident 30/04/2023 12:03 (SGT) Exact Location of Accident Singapore Additional Location Information **CLEMENTI LOOP** Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number **GBB2407M**

INSURED/POLICYHOLDER

Is company? Yes

Name Of Registered Owner TARGET SERVICES ENGINEERING CO PTE LTD

VEHICLE PARTICULARS

Manufacturer Nissan Model Cahstar

Variant

Vehicle Category Commercial vehicle

Transmission Manual 2953

INSURANCE COMPANY

Name of Insurance Company Lonpac Insurance Bhd Policy Number / Cover Note Number Z22VC05012269

DRIVER

Name of Driver JAHAR UDDIN ABDUL KADIR Passport No/FIN G8180306X

Address ATRIX, 82 LORONG 23 GEYLANG

Address complement # 03-01 Postcode 388409 Does Driver Own Other Vehicles?

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear

Weather Conditions	Clear
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Was anybody injured in the Accident? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement	No No Yes 1
CIRCUMSTANCES OF ACCIDENT	

PLEASE REFER TO THE ATTACHED STATEMENT

*Report was unable to submit on 02.05.2023 as Gear system was down."

ATTACHMENT(S)

Are accident photos available for attachment?

Yes
Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration NumberXD4695MVehicle Manufacturer-Vehicle Model-Vehicle Variant-Vehicle Colour-Vehicle CategoryCommercial vehicleName of Driver-Insurance Company Name-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number XB8480A

Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category Commercial vehicle

Name of Driver TAO XIAOJIAN

Insurance Company Name -

SKETCH PLAN

IMPORTATION NOTICE


- 1. PIBES About correctly the details of the accident to speed up the claims process.
- 2. This # mirrust be completed by the Polipyholder and/or the Actual Driver.
- Inform On provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wiful misrepresentation or withholding of material facts may allow insurable companies to <u>repudiate policy liability</u>.
- 4. The 1= 3e and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any like reporting may be referred to the Traffic Police Department for investigation.
- By the logement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
 report Long made available aforesaid.
- B. Conserpluser the Personal Data Protection Act (PDPA)
- I understain, acknowledge, agree and consent that:
- (a) My Institute, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or procles my personal date/personal information and in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have Intured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident that be collective by related to as the "insurers"), the insurers' lewyers/law firms, the Monetary Authority of Singapore and any relevant government igency/authority (such as the police), for the purpose(s) of:
- (i) processins hardling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) Investigating the accident and/or my claims;
- (iii) carryling oil and/or dealing with my instructions or responding to any enquiries by me;
- (iv) admin isteing my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of tertain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail.
- (v),comptying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively te "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose ind/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including software), which may be sited outside of Singapore, for one or more of the above Purposes.

olloyholder's Senature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

| Company | Comp



On the above stated date and time, I was travelling along clementi avenue 6. I was on the 3rd lane and vehicle C was in front of me towing vehicle B. The traffic signal ahead of me was red so vehicle C slowed down and came to a complete stop. At that point of time, my water bottle fell to my brake pedal. I tried to brake but I couldn't brake on time, and I hit Vehicle vehicle B. no damages to vehicle C.

A - GBB2407M

B - XD 4695M

C- XB 8480A

D.O.A- 30/04/2023 @ 12.03PM




5/2/23, 4:29 PM

Clementi Ave 8 - Google Maps





Image capture: Dec 2022 © 2023 Google





https://www.google.com/maps/@1.3265979,103.7642135,3a,90y.160.85h,46.96t/data=l3m7!1e1l3m5l1s8UBCGm7KceBTNiA0_Lc7SQl2e0l6shttps:%... 1/1





















IMPORTANT NOTE: Please submit the completed Addendum form to the same Accident Reporting Centre with whom you submitted the Original Report.

	ADDENDUM
A)	P ARTICULARS OF PERSON MAKING THE AMENDMENTS:
	o riginal Report No: SN09 2353 000D Vehicle Registration No: GBB 2407M
	N 2me (as shown in NRIC): Jahar Uddin Abdul Kadir NRIC/FIN/Passport No: (1818 0306×
	(**Vehicle Driver/ Policyhold er) (*) Please delete as appropriate
	Addiress: Atrix, 82 Jorong 23 Geylang # 03-01 Singapore (388409)
	Contact (Tel): Mobile No.:9398 1334
	Ernail Address: Sales. vtech waterproofing agmail-com
	Date of Accident: 30 04 2023 Time of Accident: 12:03
	Place of Accident: Clement Joup
	In surance Company:ONPAC
B)	ACDITIONAL INFORMATION /AMENDMENTS:
	I have made a report on the above-mentioned accident and would like to include additional information or make the following amendments:
	And of the man to the terms of the
	(Grandle was a state of
	- January Plan.
	which c - XB' 8480 A

Policyholder / Actual Driver's Signature Date: Reporting Centre Personnel's Signature Name (as in NRIC/ID card): Date:

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

GBB2407M

Date of Accident

01/05/2023

Reset

% RESULT & RECEIPT

TP Insurer Enquiry Insurance Lonpac Insurance Bhd Period of Insurance 10/06/2022 - 07/06/2023 Requested By KSCGP02 (KSCGP JURIS LLP) Requested Date 03/05/2023 15:43

Payment details

Request Amount: **\$\$1.85** GST Amount: **\$\$0.15**

Total Amount Due (GST Inclusive): **\$\$2**

General Insurance Association

Records Management Centre GST Registration No: **M400017735**



Enquire Vehicle's Insurance Particulars (As At 30 Apr 2023 / 11:30:00)

Vehicle No.: Make Description/Model:

GBB2407M NISSAN / CABSTAR 3.0 5M/T ABS 2DR 2WD

3.41

Insurance Company Name:

LONPAC INSURANCE BHD

Business Transaction Reference No.:

20230506082303275298

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).



Registered Address Type:

Free Format

Enquire Vehicle Owner Details (As At 30 Apr 2023 / 11:30:00)

Vehicle Owner Details

Owner ID Type: Owner ID:

Company 198301417M

Owner Name:

TARGET SERVICE ENGINEERING CO PTE

LTD

Registered Block/House No.: Registered Street Name:

32 LORONG 23 GEYLANG

Registered Unit No.: Registered Building Name:

#03-01 ATRIX

Registered Postal Code:

388409

Vehicle Insurance Details

Vehicle No.: Make Description/Model:

GBB2407M NISSAN / CABSTAR 3.0 5M/T ABS 2DR 2WD

3.4T

Insurance Company Name:

LONPAC INSURANCE BHD

Printed on 08 May 2023 11:26:22

Copyright © Land Transport Authority of Singapore 2023



You have successfully logged out.

Your last login date and time was 06 May 2023, 08:19:05.

To return to ONE.MOTORING, please click here

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	GBB2407M	18.19 Enquire Veh Owner Info	26.75	06 May 2023 /
			(Others) by Law Firm		08:23:03