

HIN TAT AUGUSTINE & PARTNERS

UEN NO. 53130863D

Advocates & Solicitors Commissioners For Oaths Notaries Public

20 UPPER CIRCULAR ROAD
#02-10/12 THE RIVERWALK
SINGAPORE 058416
TEL : (65) 6533 0212
FAX : (65) 6533 0313

WEBSITE: www.htapartners.com.sg
WRITER : MARILYN HO SU FEN (marilyn@htapartners.com.sg)
SECRETARY : RUBY ONG (ruby@htapartners.com.sg)

In Association with:
Stroh Legal Group Pte Ltd
International Legal Consultants

(65) 6533 0163 (Direct Fax)

Service By Fax Not Accepted

Our Ref : TCL.MH.ro.50044.22.at

Your Ref : S2M03SS3

24 May 2022

Comfort Transportation Pte Ltd
383 Sin Ming Drive
Singapore 575717

By Certificate of Posting (w/o encl)
(for your information only)

AXA Insurance Pte Ltd
9 North Buona Vista Drive
#18-01/06 Tower 2
The Metropolis
Singapore 138588
Attn : Motor Claims Department

By email

Dear Sirs

ACCIDENT INVOLVING SGT 7524X & SHB 6716Z ALONG ECP TOWARDS CITY (BEFORE MARINE PARADE EXIT) ON 7 FEBRUARY 2022 @ 0830HRS

We act for Autorent Leasing Pte Ltd, the owner of motor vehicle no. SGT 7524X, in relation to the above-captioned road traffic accident.

We are instructed that you were the owner and/or the insurers of motor vehicle no. SHB 6716Z at the material time. We are further instructed that the accident was caused by your authorized driver and / or your insured driver's negligence in the driving, control and/or management of your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

1. Cost of Repairs	S\$16,600.00
2. Loss of Use (14 days x S\$120.00/day)	S\$ 1,680.00
3. Survey Report Fees	S\$ 1,045.00
4. LTA Search Fee	S\$ 7.49
5. Costs (inclusive of GST)	S\$ 1,070.00
6. Incidentals	<u>S\$ 50.00</u>
Total	<u>S\$20,452.49</u>

.../Page 2

TAN HIN TAT
AUGUSTINE SOH KHENG YEOW
SEAN LIM THIAN SIONG
TANG CHI LOONG

TAN E-FANG
CLAIRE THAM LI MEI
HO KIM FOONG

CAROLYN LIM MAY LEAN
SERENA GOH MAE LI
GONG CHIN NAM
MOHD ZIKRI B MOHD MUZAMMIL
MARILYN HO SU FEN
QUAY WEE MENG ANDRED
MADELINE EE ZI RUI
ISABELLE NINA CHEN WENXI
BRANDON LIM XING WEI

CONSULTANTS: LIM KIA TONG
JANET WEE-TAN

 **eLitigation**

HIN TAT AUGUSTINE & PARTNERS

Page No. 2

Our Ref. TCL.MH.ro.50044.22.at

Your Ref. S2M03SS3

Date : 24 May 2022

The following supporting documents are enclosed herewith: -

1. Copy of Singapore Accident Statement by SGT 7524X;
2. Copy of Final Repair Bill from AT Performance;
3. Copy of LTA Tax Invoice & search result of SHB 6716Z;
4. Copy of Survey Invoice & Survey Report from ST Appraisal Services; and
5. **192 pcs of original** photographs of motor vehicle no. SGT 7524X.

Please note that you / your authorized driver and/or your insured driver should send to us an acknowledgement of receipt of this letter within **fourteen (14)** days of receipt of this letter, failing which our client will have no alternative but to commence proceedings against you/ your authorized driver and/or your insured driver without further notice to you / your authorized driver and/or your insured driver.

Please note that if you / your authorized driver and/or insured driver have a counterclaim against our client arising out of the accident, you / your authorized driver and/or your insured driver are also required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within **eight (8)** weeks of your receipt of this letter.

Please note that our client's claim is in respect of its property damage claim and is strictly without prejudice to the uninsured losses and/or injury claim (if any).

Yours faithfully



MARILYN HO SU FEN

Enc.

cc: client

Enquire Vehicle Owner Details (As At 07 Feb 2022 / 08:30:00)

Vehicle Owner Details

Owner ID Type:

Company

Owner ID:

199303821R

Owner Name:

COMFORT TRANSPORTATION PTE LTD

Registered Address Type:

Private Residential (Condo Apt or House) /
Shopping / Office Complexes

Registered Block/House No.:

383

Registered Street Name:

SIN MING DRIVE

Registered Unit No.:

-

Registered Building Name:

GAS BUILDING

Registered Postal Code:

575717

Vehicle Insurance Details

Vehicle No.:

SHB6716Z

Make Description/Model:

MERCEDES BENZ / VIANO 2.2 CDI TREND
LONG

Insurance Company Name:

AXA INSURANCE PTE LTD



Thank you

Tang Chi Loong has successfully logged out.

Your last login date and time was 07 Feb 2022, 15:59:43.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)
1	Vehicle	SHB6716Z	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49

FINAL REPAIR BILL
REF.: TP/140270/324027524

A T PERFORMANCE

160 SIN MING DRIVE #07-19 SIN MING
AUTOCITY SINGAPORE 575722


TEL: 6453 5112
FAX: 6552 2061

Regn. No. 53413556X

Messrs. Autorent Leasing Pte Ltd Date 14/3/22

Vehicle No. SGT7524X Kia Forte K3 1.6A

Quantity	Items/Descriptions	Prices
	Lump Sum Repair Basis As Recommended.	16,600.00
	<i>SGD.: Sixteen Thousand Six Hundred Only.</i>	
Total:		\$16,600.00



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/02/2022 11:45 (SGT)
Date of Accident	07/02/2022 08:30 (SGT)
Exact Location of Accident	ECP, Singapore
Additional Location Information	ECP towards city (B/F Marine Parade Exit)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGT7524X
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Autorent Leasing Pte Ltd
Company Reg No	202059595H
Email Address	operations@alautocar.sg
Mobile Phone No	(Phone) +65-93377960
Alternative Phone No	(Home) +65-93377960

VEHICLE PARTICULARS

Manufacturer	Kia
Model	K3
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5118839941-01-000001
Cover Note Number	-

DRIVER

Name of Driver	Lee Beng Wah
NRIC No	S7230511F

Date Of Birth	26/08/1972
Occupation	Outdoor
Date Of Driving Pass	18/04/1994
Driving experience	27 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93377960
Alt. Phone Number	-
Email Address	operations@alautocar.sg
Address	Blk 120A Edgedale Plains #16-277
Address complement	-
Postcode	821120
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	unknown
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Refer attached report

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB6716Z
Vehicle Manufacturer	Mercedes
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi

Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SFE7522S
Vehicle Manufacturer Audi
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category Private car
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
Policyholder's Signature / Date & Time

[Signature]
Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]
Witnessed by Reporting Centre Personnel

Sketch Plan

ECF TOWER CITY (R/F MARK PARADE EXIT)

7

10/10/2010

←

(P) SGT 7524X
(S) SH867163
(C) SFE 75225
(D) SCM 8369E

Describe Circumstances of the Accident

I WAS TRAVELLING ALONG ECP TOWARDS CITY ON THE RIGHT MOST LANE.
 I APPLIED E-BRAKE DUE TO THE FRONT CAR TAKING A TURN.
 SHOOTER CAME FROM BEHIND AND HIT INTO MY CAR REAR SECTION CAUSING
 MY CAR TO MOVE FORWARD AND HIT INTO STEPSIDE AREA SECTION.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel































Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
ROAD TRANSPORT (AMENDMENT) ACT, 2019 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5118839941-01-000001

Cover : drivo CLASSIC

1. Index mark and Registration Number of Vehicle : **SGT7524X**
Chassis Number : KNAFX411MH5668698
2. Name of Policyholder : AUTORENT LEASING PTE. LTD.
3. Effective Date of Insurance : 28 Aug 2021
4. Expiry Date of Insurance : 27 Aug 2022
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

- (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
(b) Use for the carriage of goods (other than samples) in connection with any trade or business.
(c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Policy, the Schedule, Endorsement and the Certificate of Insurance are to be read together as one document.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: AL AUTOCAR PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : S & M ALLIANCE PTE LTD (00000614373)

Date of Issue : 26 Aug 2021 10:36 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Chief Executive

Appraisal Services

Insurance Loss Adjusters & Licensed Appraisers

Insurance Claim Investigator

Business Address: 60 Arab Street Singapore 199757

Tel: 98586761 / 96786893; Fax: 6297 0270

E mail - ttrajan.stappraisal@gmail.com

Mailing Address: 161 Alexandra Post Office Singapore 911506

Invoice No : **06260**

ORIGINAL

INVOICE

Date : 25 Feb 2022

Our Ref : TP / ATP SGT7524X/ 02.07/22

Your Ref :

CUSTOMER PARTICULARS

Name	:	M/s Autorent Leasing Pte Ltd
Address	:	C/o 160 Sin Ming Drive
		#07-19 Sin Ming Autocity
		Singapore 575722

ASSIGNMENT

TP Motor Claims by SGT 7524 X

DESCRIPTION

A set of Survey Report, correspondence & consultation. Other disbursements incurred. Transport charges.


TOTAL

Terms of payment: 7 days from date of invoice
All Payments please make payment to "ST Appraisal Services"

AMOUNT CHARGEABLE

\$1,045.00

\$1,045.00


Authorised Signature

Appraisal Services

Insurance Loss Adjusters & Licensed Appraisers

Insurance Claim Investigator

Business Address: 60 Arab Street Singapore 199757

Mobile: 98586761 / 96786893 Fax: 62970270

Mailing Address : 161 Alexandra Post Office Singapore 911506

Email: ttrajan.stappraisal@gmail.com

Date : 25th Feb 2022

Our Ref : TP / ATP SGT7524X/ 02.07/22

Your Ref :

M/s Autorent Leasing Pte Ltd

C/o 160 Sin Ming Drive

#07-19 Sin Ming Autocity

Singapore 575722

DAMAGED VEHICLE (SGT 7524 X) INSPECTION REPORT (WITHOUT PREJUDICE)

Detailed accounts of our inspection are as follows:-

(A) Reference

Name of Claimant	: M/s Autorent Leasing Pte Ltd	Date of Request	: 9 th Feb 2022
		Referred By	: Person in charge
Policy No.	: Please Advice	Date of Inspection	: 9 th Feb 2022
Claim No.	: Please Advice	Date of Re-inspection	:
Accident Date	: 7 th Feb 2022	Sum Insured	: NA
Repairer	: M/s AT Performance	Excess Amount	: NA
	160 Sin Ming Drive #07-19	3 rd Party Vehicle	: Please Advice
	Sin Ming Autocity, Singapore 575722	3 rd Party Insurer	: Please Advice

(B) Particulars of Vehicle


Registration No	: SGT 7524 X	Mileage	: 118255 Km
Make & Model	: KIA FORTE KE 1.6A	Engine No	: G4FGGH658482
Date of Registration	: 31 st Oct 2016	Chassis No.	: KNAFX411MH5668698
Colour	: Grey	Engine Capacity.	: 1,591 cc

(C) Pre-Accident Condition (Static Test Only)

Steering	: Serviceable	Paint Work	: Fair
Foot-brake	: Serviceable	Modification	: NIL
Hand-brake	: Serviceable	General Condition	: Fair

(D) Tyre Condition

	Tread Depth	Make	Size
Front Left	60 %	ECO 809 RAPID	205/55 R16
Front Right	60 %	ECO 809 RAPID	205/55 R16
Rear Left	60 %	ECO 809 RAPID	205/55 R16
Rear Right	60 %	ECO 809 RAPID	205/55 R16

(E) Point of Impact**(F) General Description of Damages**

The impact of the collision has damaged/affected the boot lid, rear bumper, rear end panel, tail lamp, parking sensor, front bumper, headlamps, air con condenser, radiator, front support panel and etc.

Please refer to the Annex for a detailed account of the damages and photographs taken.

(G) Recommendation

We have inspected thoroughly the actual damages found on the vehicle, before we arrived at our recommendation as to whether the parts needed replacement or repairs.

Our adjusted cost of lump sum repair is **\$16,600.00** and an estimated **12** days is required to repair the vehicle. Please refer to the Annex for a detailed account of the cost estimates.

(H) Remarks

We have not authorised the repairs. However for information, under normal circumstances, the repairs should not exceed **12** days.

This inspection was conducted on a “**without prejudice**” basis.

We are pleased to advice that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

ST Appraisal Services



T T RAJAN
MVI, ITC (Mechanical), NTC (Motor Vehicle)
ASIET, MSAAA, Assessor/Appraiser
AD041-2007532D

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SGT 7524 X**Adjustment of Spare Parts Costs for Repairs**

Item	Qty	Vehicle parts description	Condition / Remark	Estimated by workshop	Disc. (%)	Adjusted cost
1	1	Bootlid	buckled	988.35	10	889.52
2	1	Bootlid logo	necessary	98.00	10	88.20
3	1	Bootlid emblem - 'CERATO'	necessary	74.60	10	67.14
4	1	Bootlid emblem - 'K3'	necessary	101.00	10	90.90
5	1	Bootlid emblem - 'FORTE'	necessary	78.00	10	70.20
6	1	Bootlid weatherstrip	cut/torn	227.50	10	204.75
7	1	Bootlid lock	malfunction	196.20	10	176.58
8	2	Bootlid lamp	cracked	946.20	10	851.58
9	2	Bootlid hinge	serviceable	156.00	100	0.00
10	1	Bootlid insulator	serviceable	349.00	100	0.00
11	1	Bootlid insulator clip - set	necessary	36.00	10	32.40
12	2	Taillamp	smashed/cracked	1462.80	10	1316.52
13	1	Rear bumper	cut/torn	721.00	10	648.90
14	1	Rear bumper reinforcement	fractured	461.20	10	415.08
15	2	Rear bumper reinforcement bracket	dented	344.00	10	309.60
16	2	Rear bumper reflector	cracked	210.00	10	189.00
17	1	Rear bumper lower garnish	cracked	364.90	10	328.41
18	2	Rear bumper side holder	affected	196.20	10	176.58
19	3	Rear bumper lower bracket	damaged	180.00	10	162.00
20	1	Rear bumper clip - set	essential	51.60	10	46.44
21	1	Rear end panel	dented	839.10	10	755.19
22	1	Rear end panel top garnish	folded/damaged	431.60	10	388.44
23	1	Rear end panel top garnish clip - set	necessary	25.60	10	23.04
24	1	Rear fender inner trim	serviceable	475.10	100	0.00
25	1	Spare tyre panel board	folded	631.40	10	568.26
26	1	Front bumper	cut/torn	796.00	10	716.40
27	1	Front bumper foam	torn	168.30	10	151.47
28	1	Front bumper reinforcement	fractured	357.00	10	321.30
29	1	Front bumper clip - set	essential	46.20	10	41.58
30	2	Front bumper side retainer	affected	136.00	10	122.40
31	1	Front bumper lower grille	cracked / torn	215.00	10	193.50
32	2	Front bumper fog lamp	cracked	490.00	10	441.00
33	1	Front bumper number plate garnish	torn	96.10	10	86.49
34	1	Front bumper logo	necessary	69.30	10	62.37
35	1	Front grille assembly	cracked	416.20	10	374.58
36	2	Front bumper inner air guide	cut/torn	194.00	10	174.60
37	2	Headlamp assembly	cracked	2408.00	10	2167.20
38	1	Front support panel	fractured	776.00	10	698.40
39	1	Front support panel top garnish	cracked	186.00	10	167.40
40	1	Radiator top panel	bent / dented	246.00	10	221.40
41	1	Air con condenser	punctured	922.00	10	829.80
42	1	Radiator assembly	dented	1018.00	10	916.20

Special nett item

1	2	Front licence plate	damaged	60.00	50.00
2	1	Bootlid label	necessary	30.00	30.00
3		Rear bumper parking sensor	malfunction	260.00	220.00
4		Rear end panel sealant	necessary	60.00	50.00
5		Radiator coolant	necessary	45.00	40.00
Total parts				18640.45	15874.82

Adjustment of Labour Costs for Repairs

To remove and replaced rear damaged parts including straightening and repositioning replacement parts.	1450.00	1300.00
To remove and replaced front damaged parts including straightening and repositioning replacement parts.	1250.00	1100.00
Supply paint material and to respray replaced and affected panels - rear section.	1350.00	1200.00
Supply paint material and to respray replaced and affected panels - front section.	950.00	750.00
To check wiring at the damaged section for proper functions.	120.00	100.00
To carry out anti-rust treatment.	150.00	120.00
To remove and install boot compartment fittings and attachments to facilitate repair.	120.00	100.00
To remove and replace air con condenser.	140.00	120.00
Install rear bumper sensor and check for proper functions.	80.00	60.00
Total labour	5610.00	4850.00

Adjustment Parts and Labour Costs of Repairs

	Estimated by workshop	Adjusted cost
TOTAL PARTS COSTS	18640.45	15874.82
TOTAL LABOUR COSTS	5610.00	4850.00
TOTAL REPAIR COSTS	24250.45	20724.82

ADJUSTED REPAIR COST**16600.00**