ASS. REC. BY: Taufik | REF: CS/ICS23007418 / Thys

ASSIGNMENT

2024 Nov

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $5000

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP PRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: F88 IIS. Yr Regn: 2005, Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Wave 125 c.c 125

Colour: Orange A/C: Insured / Std / NI / NA

Sp.Reading: 22910 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NF125MP0028482

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NM / S/Rim / STD A/Rim or

Tyre Size: F: 80/90R17

R: 90/80R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Sportivo

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	mm	L/Bal.	mm
D.O.A.		D.O.I.	21/7/23 @ 450pm

Survey held at Sang Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair Range : $3500 – 4500, 6 days.

Date/Time, File Pass to? [ ] : Preli. Report

1) _____ [ ] : Final Report

Date/Time, File Return to?

2) _____

Report Format : _____

Lump Sum / I.B.I. ($ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: [ ] : Site Insp ($ _____)

[ ] : Interview ($ _____)

[ ] : Tech. Invs ($ _____)

[ ] : Weekend ($ _____)

Survey Fee:	
Transportation: ___S + RS___SI	
Photos	
Others	
TOTAL	