

2024 Nov

Veh No: F88115. Yr Regn: 20.5 / Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Florida Wave 125 c.c. 125

Colour: Orange A/C: Insured / Std / NI / NA

Sp. Reading 22968 T/Radio; Insured / Std / NI / NA

Eng/No: 28142

C/No: NF125MPO340152

Gen. Cond: Good / Fair / Poor / Burnt

Sleering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: RM / S/Rim / STD A/Rim or

Tyre Size: F: 80/90 R17

R: 90/80 K17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO/YOKO or *Spartivo*

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 21/7/23 @ 430pm

Survey held at Saugus Me. For

Des. of Damages : Front / Rear / O/S / N/S / U/G / Rooftop - or

The U/C / Chassis frame / Body Structure affected due to collision.

Report Range: \$3500 - 4500, 6 day.

☐ : Prel. Report

Final Report

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

□	Interview	(\$
---	-----------	-----

□: Tech. Invs (\$

☐ : We have (5)

Survey Fee:

Transportation:

$$S + RS \rightarrow S$$

} Photos

5) Others

TOTAL

Not Filled:

Lump Sum / L.S. / \$