

SMRT Accident Vehicle Repair Estimates

SMRT A
80 Wood
FAX Nu
Estimate
Acciden

Date Ge
User ID

Section A - Accident Details

Registration Number	SHB741P
Case Reference Number	TAX/07/23/2059
Registration Date	10/10/17
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	JURAIMI BIN JOHARI
Type of Accident	Head to Rear
Accident Date and Time	20/7/23 7:00 PM
Accident Reported Date and Time	21/7/23 11:50 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118927
Special Instruction to ARC, if any	REAR PORTION
Prepared Date and Time	21/7/23 1:35 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$0.00
Total Spray Cost	\$1,038.00	\$0.00
Total Spare Part Cost	\$2,071.98	\$0.00
Total Other Cost	\$500.00	\$0.00
TOTAL COST	\$4,285.98	\$0.00
Lump Sum Total	\$4,300.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	21/07/2023 1:46 PM	
Signature		
Remarks		

Tarikh
97495749
wp' 21/7/23
US Repair after
repair
tarikh e
khantun
2 days

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

 SMRT #
 60 Wood
 FAX Nu
 Estimatr
 Acciden

Date Ge

User ID

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if appl
TO REPAIR REAR PORTION	\$676.00	200
Total Labour	\$676.00	

Part 2 - Spray Painting & Panel Beating Related Works

200

Job Scope	Quotation from ARC	Adjusted by Surveyor, if appl
TO RESPRAY FILLER RR BUMPER LH	\$220.00	X nn
TO RESPRAY BUMPER BEAM	\$220.00	X nn
TO RESPRAY REAR BUMPER	\$378.00	200
TO RESPRAY REAR PANEL	\$220.00	X nn
Total Spray Painting & Panel Beating	\$1,038.00	200

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if appl
TO WASH AND VACUUM	\$60.00	X nn
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	X nn
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	X nn
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	20
TO REPLACE SUNDRY PARTS	\$100.00	X nn
Total Other Costs	\$500.00	30

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor
		5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$16.70	25.00	\$12.52	Replace X nn	
		8999730100	ANTENNA, ELECTRICAL KEY	1.00	\$78.00	25.00	\$58.50	Replace nn X	
		9018906029	REAR BUMPER GROMMET SCREW	1.00	\$2.20	25.00	\$1.65	Replace nn	
		8159147010	LENS & BODY ASSY, RR BUMPER, LH	1.00	\$544.40	10.00	\$489.96	Replace nn Y	
		5839947030	COVER, REAR FLOOR UNDER, LH	1.00	\$261.60	25.00	\$196.20	Replace nn X	
		6625947010	COVER, REAR FLOOR UNDER CENTER	1.00	\$249.10	25.00	\$186.83	Replace nn X	
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace nn	
		5202347030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace nn	
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace nn	
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace nn	
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$4.30	25.00	\$6.45	Replace nn	
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace nn	
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace nn	
		5256647900	FILLER, RR BUMPER, LH	1.00	\$168.60	25.00	\$126.45	Replace X nn	
		5259968030	STOPPER, RR BUMPER, RH & LH	1.00	\$4.80	25.00	\$3.60	Replace nn X	
		5257647040	RETAINER, RR BUMPER, LH	1.00	\$127.40	25.00	\$95.55	Replace nn	
		5259247040	SEAL, RR BUMPER, LH	1.00	\$95.50	25.00	\$71.63	Replace X nn	
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace nn	

SMRT Accident Vehicle Repair Estimates

SMRT A
60 Wood
FAX Nu
Estimate
Acciden

Date Ge

User ID

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor
		5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$707.10	25.00	\$530.33	Replace X nn	
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace Rel	
		5219147030	SEAL, RR BUMPER ARM, RH & LH	1.00	\$12.30	25.00	\$9.23	Replace Xnn	
Total					\$3,930.40		\$3,120.31		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor
Total									

1164.98
430
1594.98
l/s\$1250
2 days #