

Ass. By: _____

REP: _____

ASSIGNMENT

From: _____ Date: _____

Estim. Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To In Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claim No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMZ7083Z Yr Regn: 2016 , Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6 Avant s.c. 1798

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 124487 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU2224G66N106603

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 255/35R19

R: 255/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 21/07/23

Survey held at

Advence

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rees N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP NL

COE Expiry :

Estimate given during : Yes ()
1st Survey : No (✓)

MV :

PV :

Nett :

819B

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

S + RS: _____ SI

Photos

Others

Report Format: _____

Report Form / L.P. / C