

ASSIGNMENT

COE-2025/may

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV


To Inspect Vehicle No: ABD 8149Hat Workshop m/s RIDE NOWof 1, BURST BAYON CRESCENT #4-40Insured: SMK 6724T 111Policy No. D21MFL0000447_02Claims No. MFL2023D0005251

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 26K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: ABD 8149HYr Regn: 2015 / MAY

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HILUX 3.0 D4DSEL c.c. 2992Colour: GREEN A/C: Insured / Std / NI / NASp. Reading: 332031 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KOH 2015017665Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NW / S/Rim / STD A/Rim orTyre Size: F: 195R15CR: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 08/05/23 D.O.I. 11/05/23Survey held at RIDE NOWDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 15KESTIMATE RANGE OF REPAIR / NO. OF DAYS (4K-5K) / 6 days

16/5/23 Submit PRS

2/8/23 Submit LS \$4950 (red 1900, 27%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2) 2/8/23-typist

Days Of Repair: 7

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS \$ SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Owner Details	
Owner ID Type:	Company
Owner ID:	341E
Vehicle Details	
Vehicle No.:	GBD8149H
Vehicle to be Exported:	No
Intended Deregistration Date:	15 May 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 3.0 DX DIESEL TURBO MT 2WD LGV
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2500400
Chassis No.:	KDH2015017065
Maximum Power Output:	-
Open Market Value:	\$28,125.00
Original Registration Date:	28 May 2015
First Registration Date:	28 May 2015
Transfer Count:	3
Actual ARF Paid:	\$1,407.00
PARF Eligibility Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE and PARF Vehicle Details	
COE Expiry Date:	27 May 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$52,001.00
COE Rebate Amount:	\$10,567.00
Total Rebate Amount:	\$10,567.00

The information contained herein is correct as at 15 May 2023

OK