

(08/11/13) W91

ASS. REC. BY: ASW

REF:

CS/CTI 23007463(Rap3)

2014

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 75062

at Workshop m/s CONVINCE

of 29, FIRST LOKYAM RD

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: SLK

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lam Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLD 75062

Yr Regn: 2016 Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA ALTIS 1.6 CVT c.c. 1598

Colour: GREEN

A/C: Insured / Std / NI / NA

Sp. Reading: 153512

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053REH 1045 49442

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 18/07/23

D.O.I. 25/07/23

Survey held at

CONVINCE AUTO

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 22K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

) S + RS. SI

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

TOTAL



M/S: China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Tel: Fax: -

Attn: Motor Claim Department

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

GST Regn No.: 202103677N

Co. Regn No.: 202103677N

Estimate No.: E2307003

Date: 21/07/2023

Accident Date: 19/07/2023

Claim No.: Third Party Claim

Policy No.: SP2003895122-01

Chassis No.: MR053REH104549442

Year: 2016

Make & Model: Toyota Corolla Altis 1.6

Vehicle No.: SLD7506Z

S/No	Description	Qty	Unit Price	Amount
List Item :				
1	Front Bumper <i>Scr</i>	1	\$ 525.00	\$ 525.00
2	Bumper Side Bracket Front RH <i>?</i>	1	\$ 105.00	\$ 205.00
3	Fender Front RH <i>bt</i>	1	\$ 660.00	\$ 660.00
4	Fender Logo <i>m</i>	1	\$ 105.00	\$ 205.00
5	Clips <i>m</i>	5	\$ 30.00	\$ 150.00
				\$ 1,745.00
<i>- List Item Discount 10% 25%</i>				\$ 174.50
				\$ 1,570.50
Special Nett Item :				
1	Spray Paint (Front Bumper & Front Fender)	1	\$ 580.00	\$ 580.00 <i>400</i>
				\$ 580.00
Labour :				
1	Dismantle Side Mirror RH Head Lamp, Front Bumper, Tyre, Tyre Mudguard For Cutting Fender & Welding On New Fender	1	\$ 850.00	\$ 850.00 <i>400</i>
2	Dismantle And Replace New Bumper	1	Inclusive	Inclusive
3	Replace Damage Parts	1	Inclusive	Inclusive
Labour Item :				\$ 850.00
TOTAL :				\$ 3,000.50
GST 8% :				\$ 240.04
Total Amount :				\$ 3,240.54

Florence

CONVINCE ENGINEERING PTE LTD

CONVINCE ENGINEERING PTE LTD

29 First Link, Yew Road, Singapore 629736

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	207G
Vehicle No.:	SLD7506Z
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jul 2023
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZRY280958
Chassis No.:	MR053REH104549442
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,990.00
Original Registration Date:	28 Jun 2016
First Registration Date:	28 Jun 2016
Transfer Count:	1
Actual ARF Paid:	\$19,990.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2026
PARF Rebate Amount:	\$11,994.00
COE Expiry Date:	27 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,200.00
COE Rebate Amount:	\$16,115.00
Total Rebate Amount:	\$28,109.00

The information contained herein is correct as at 26 Jul 2023

OK

Toyota Corolla Altis 1.6A

\$50,800 Instalment \$1,166/mth

PREMIUM AD



 Shortlist

 Get Warranty

**KONNICHIWA! TOKYO AWAITS!**

One-way from
\$240*

Book now
*Taxes included. Terms apply.


JNTO

Overview

Financial

Photo

Research

Depreciation	 \$14,490 / year
Reg. Date	25-May-2016 (2yrs 9mths 28days COE left)
Manufactured	 2015
Mileage	-
Transmission	Auto
Engine Cap	1,598 cc
Road Tax	 \$742 / year
Power	90.0 kW (120 bhp)
Curb Weight	 1,205 kg
COE	 \$47,020
OMV	 \$19,589
ARF	 \$19,589
Dereg Value	 \$25,061 as of today
No. of Owners	 2
Type of Veh	Mid-Sized Sedan