

ASS. REC. BY: [Signature]


REF: CS/HLA 23007468/Rvy³

3734

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMN 494E
 at Workshop m/s MOVA
 of BUKIT MERBA
 Insured: FLA
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMN 494E Yr Regn: 2019 / JULY
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: NISSAN SYLPHY 1.6 CVT c.c. 1598
 Colour: BLUE A/C: Insured / Std / NI / NA
 Sp. Reading: 88756 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MNTB6AB1720055711
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 175/60R16
 R: 175/60R16



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 19/07/23 D.O.I. 24/07/23
 Survey held at MOVA (BM)

Bal. or Market Value: 83k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lrm Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
REPAIR LIM RI - 53K

Date/Time, File Pass to? : Prell. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Format : _____
 Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS. SI _____
 Photos _____
 Others _____
 TOTAL _____



TP INSURER:
UNKNOWN

HL Assurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	19/07/2023
Vehicle Reg. No.:	SMN494E	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	NISSAN SYLPHY, 1.6 CVT (A)	Vehicle Reg. Date:	24/07/2019
Vehicle Colour:	BLUE	Chassis No:	MNTBBAB17Z0035711
Engine No:	HR16942552C		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	4,780.75
Miscellaneous Items	0.00
Labour	1,340.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,120.75
+ GST 8.00% (S\$)	489.66
Nett Amount (S\$)	6,610.41

This claim is handled by: BILLY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 21 Jul 2023)

Parts: 143

NISSAN SYLPHY 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMN494E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RADIATOR GRILLE <i>Com</i>			
2	1		*RADIATOR GRILLE LOGO <i>Com</i>	0.00	0.00	*630.00 F
3	10		*TOP GARNISH CLIPS <i>Com</i>	0.00	0.00	*80.00 F
4	2		*HEADLAMP ASSY RH & LH <i>Com</i>	0.00	0.00	*30.00 F
5	2		*HEADLAMP LOWER BRACKET RH <i>?</i>	0.00	0.00	*1,500.00 F
6	1		*FORNT BUMPER <i>Com</i>	0.00	0.00	*190.00 F
7	1		*FRONT BUMPER SPONGE <i>Com</i>	0.00	0.00	*600.00 F
8	1		*FRONT BUMPER REINFORCEMENT <i>?</i>	0.00	0.00	*350.00 F
9	1		*FRONT BUMPER LOWER GRILLE <i>?</i>	0.00	0.00	*480.00 F
10	2		*FRONT BUMPER RETAINER RH & LH <i>Com</i>	0.00	0.00	*140.00 F
11	10		*FRONT BUMPER CLIPS <i>Com</i>	0.00	0.00	*80.00 F
12	1		*FRONT BUMPER PLATE <i>Com</i>	0.00	0.00	*30.00 F
13	1		*FOG LAMP RH <i>X</i>	0	0.00	*40.00 FS
14	1		*FOG LAMP GARNISH RH <i>X</i>	0.00	0.00	*330.00 F
15	1		*SUPPORT PANEL (REPAIR)	0.00	0.00	*75.00 F
16	1		*FRONT FENDER RH (REPAIR)	0.00	0.00	-
17	1		*REAR FENDER (REPAIR)	0.00	0.00	-
			<i>Bumper</i>	0.00	0.00	-
			<i>3000</i>			
Sub Total (\$\$)						4,555.00
+ Margin on L,N Items 5.00% (\$\$)						225.75
Total Parts (\$\$)						4,780.75

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK & STRAIGHTEN SUPPORT PANEL, FRONT FENDER, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	New	400 600.00
2	SPRAY PAINT REAR BUMPER, FRONT BUMPER, FRONT FENDER RH	New	600 600.00
3	REMOVE & REPLACE A/C CONDENSER, PIPE, HOSE & RECHARGE A/C GAS	New	100.00
4	CHECK WIRING & FOCUS HEADLIGHT	New	30 40.00
Gross Labour Cost (\$\$)			1,340.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Parau
Hp 9000068

S # deep

P/P

24/07/23

Resy before print

Consultants hence notify
 Repairer of the following:
 Resurvey before/after spray painting
 Spray damaged part(s) during resurvey
 Prices are subject to confirmation
 Party survey is on a "Without Prejudice" basis
 Legal modification(s) is allowed
 Elementary item(s) must be resurveyed and
 Subject to final approval from Insurance Company

Knownledged by Repairer
 Signature:
 e:

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	373H
Vehicle No.:	SMN494E
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jul 2023
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.6 CVT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	HR16942552C
Chassis No.:	MNTBBAB17Z0035711
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,713.00
Original Registration Date:	24 Jul 2019
First Registration Date:	24 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$16,713.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jul 2029
PARF Rebate Amount:	\$12,534.00
COE Expiry Date:	23 Jul 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,589.00
COE Rebate Amount:	\$17,131.00
Total Rebate Amount:	\$29,665.00

The information contained herein is correct as at 25 Jul 2023

OK

Nissan Sylphy 1.6A

\$83,888 Instalment \$961/mth

Apply for 2.28% loan

Shortlist

Get Warranty



Overview Financial Photo Research

Depreciation	i \$12,580 / year
Reg. Date	25-Jul-2019 (5yrs 11mths 29days COE left)
Manufactured	i 2019
Mileage	54,840 km (13.7k / year)
Transmission	Auto
Engine Cap	1,598 cc
Road Tax	i \$742 / year
Power	85.0 kW (113 bhp) View specs of the Nissan Sylphy (2018-2021)
Curb Weight	i 1,205 kg
COE	i \$26,667
OMV	i \$16,713
ARF	i \$16,713
Dereg Value	i \$28,542 as of today
No. of Owners	i 1