

**SMRT Accident Vehicle Repair Estimates**

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/08/2023

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB5014M
Case Reference Number	BUS/06/23/5041
Registration Date	1/11/2014
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Mohamad Isnin Bin Mustafa
Type of Accident	Side Swipe
Accident Date and Time	24/6/2023 8:07 PM
Accident Reported Date and Time	27/6/2023 9:07 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118976
Special Instruction to ARC,if any	SMB5014M - RIGHT FRONT PORTION GBG5489E (TP) - INSURED WITH INCOME
Prepared Date and Time	24/7/2023 10:53 AM
Chassis Number	SFD76CLR5EMTL3503
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$708.00	\$538.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$1,238.00</b>	<b>\$803.00</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Jeong Choon Hwee	Taufikh (LKK)
ARC / Surveyor Sign Off Date	24/07/2023 10:59 AM	25/07/2023 9:51 AM
Signature		Taufikh
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

**SMRT Accident Vehicle Repair Estimates**

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/08/2023

User ID : CatherineLee

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	\$530.00	\$265.00
<b>Total Labour</b>	<b>\$530.00</b>	<b>\$265.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$708.00	\$538.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$708.00</b>	<b>\$538.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011052	BODY RH	20590172/2	BUMPER,CORNER:R/H, FOR ADL E500 DD BUS	1.00	\$1,181.40	100.00	\$0.00	Repair	Repair
<b>Total</b>					<b>\$1,181.40</b>		<b>\$0.00</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									