

(06/11/13) wof

CS3

Rvp3

ASS. REC. BY: PaulREF: CC4AIS 23007486 / Rya3

828F

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / (TP) WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SNG 6994Pat Workshop m/s GOLD ANTIWORKSof 48 TOA GUAN ROAD #1-115Insured: SJY 9032Z AISPolicy No. SP2006469263-01Claims No. 2023 32010942JK

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 72K

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNG 6994PYr Regn: 2017 / DGEType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SUDARY XV 1.6 ISC.C. 1600Colour: WHITE

A/C: Insured / Std / NI / NA

Sp. Reading: 114321

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JF1H73KCSJ4026790

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

COMPETUS

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 19/07/23D.O.I. 25/07/23

Survey held at

GOLD ANTIDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 46K1/8/23 ESTIMATE RANGE OF REPAIR / NO. OF DAYS - 2K-3K / 3 days

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair: 3

1)

☐

Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2/8/23-typist

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos

Others

Report Format:

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

TOTAL

Subaru XV 1.6i-S

\$66,800 Instalment \$1,111/mth

PREMIUM AD

- ♡ Shortlist
- ✓ Get Warranty
- 📄 Loan Calculator



Overview

Financial

Photo

Research

Depreciation	ⓘ \$14,860 / year
Reg. Date	18-Jul-2017 (3yrs 11mths 21days COE left)
Manufactured	ⓘ 2017
Mileage	120,000 km (19.9k / year)
Transmission	Auto
Engine Cap	1,600 cc
Road Tax	ⓘ \$744 / year
Power	84.0 kW (112 bhp)
Curb Weight	ⓘ 1,480 kg
COE	ⓘ \$42,801
OMV	ⓘ \$15,387
ARF	ⓘ \$15,387
Dereg Value	ⓘ \$27,028 as of today
No. of Owners	ⓘ 1
Type of Veh	CUV

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	828F
Vehicle No.:	SNG6994P
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jul 2023
Vehicle Make:	SUBARU
Vehicle Model:	XV 1.6I-S AWD CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	FB16YC07063
Chassis No.:	JF1GT3KC5JG026170
Maximum Power Output:	84.0 kW (112 bhp)
Open Market Value:	\$14,500.00
Original Registration Date:	18 Dec 2017
First Registration Date:	18 Dec 2017
Transfer Count:	2
Actual ARF Paid:	\$14,500.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2027
PARF Rebate Amount:	\$10,150.00
COE Expiry Date:	17 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$15,804.00
Total Rebate Amount:	\$25,954.00

The information contained herein is correct as at 26 Jul 2023

OK