


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / (TP) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SNG 6994P
 at Workshop m/s GOLD ANTONOV
 of 48, TOA GUAN ROAD #1-119
 Insured: AIS
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 72K
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNG 6994P Yr Regn: 2017 / DGE
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: SUDARY XV 1.6 IS C.C. 1600
 Colour: WHITE A/C: Insured / Std / NI / NA
 Sp. Reading: 114321 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JF1H73KCSJ4026790
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: NIL / S/Rim / STD A/Rim or
 Tyre Size: F: 225/50R17
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or COMPETUS

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 19/07/23 D.O.I. 25/07/23
 Survey held at GOLD ANTONOV

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 46K

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - 2K-3K / 3 days

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

Subaru XV 1.6i-S

\$66,800 Instalment \$1,111/mth

PREMIUM AD

 Shortlist  Get Warranty  Loan Calculator



Overview Financial Photo Research

Depreciation	 \$14,860 / year
Reg. Date	18-Jul-2017 (3yrs 11mths 21days COE left)
Manufactured	 2017
Mileage	120,000 km (19.9k / year)
Transmission	Auto
Engine Cap	1,600 cc
Road Tax	 \$744 / year
Power	84.0 kW (112 bhp)
Curb Weight	 1,480 kg
COE	 \$42,801
OMV	 \$15,387
ARF	 \$15,387
Dereg Value	 \$27,028 as of today
No. of Owners	 1
Type of Veh	<u>CUV</u>

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	828F
Vehicle No.:	SNG6994P
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jul 2023
Vehicle Make:	SUBARU
Vehicle Model:	XV 1.6I-S AWD CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	FB16YC07063
Chassis No.:	JF1GT3KC5JG026170
Maximum Power Output:	84.0 kW (112 bhp)
Open Market Value:	\$14,500.00
Original Registration Date:	18 Dec 2017
First Registration Date:	18 Dec 2017
Transfer Count:	2
Actual ARF Paid:	\$14,500.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2027
PARF Rebate Amount:	\$10,150.00
COE Expiry Date:	17 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$15,804.00
Total Rebate Amount:	\$25,954.00

The information contained herein is correct as at 26 Jul 2023

OK