

ASS. REC. BY:

REF: A251Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 870k

IDAC Accident Report: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: 06 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: SL5 4117DYr Regn: 09, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Toyc.c. 1797Colour: M. Yellow

A/C: Insured / Std / NI / NA

Sp. Reading: 429653

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 8YX102065043Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rlm / STD / Rlm or

Tyre Size: F: 215/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Cresland

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 19/7/23D.O.I. 21/7/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S body

The U/C / Chassals frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prel. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Transportation

S - RS. SI

Fees

Others

Report Format:

Lump Sum / I.B.I. (\$)

TOTAL

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : SLS 4117 D
Make : Toyota C-HR
Year : 2017

Not Authorised
Lump Sum
Penny After Pains
6 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front n/s fender	My \$855.60	✓
1 pc	Front n/s fender innershield	Sm \$187.20	X
1 pc	Front n/s fender arch garnish	Gr \$185.70	✓
1 pc	Front n/s fender emblem	Me \$55.70	✓
1 pc	Front top bumper	Sm \$755.60	X
1 pc	Front lower bumper	Sm \$557.60	X
1 pc	Front n/s bumper side retainer	Sm \$75.10	X
1 pc	Front n/s door assy	Bl/warp \$1,450.70	✓
1 pc	Front n/s door outer protector	mi \$425.60	✓
1 pc	Front n/s door frame black sticker	Me \$85.10	✓
1 pc	Front n/s door rubber	Sm \$197.20	X
1 pc	Front n/s door inner trim board	Sm \$550.10	X
1 pc	Front n/s door glass regulator	\$255.60	?
1 pc	Front n/s door glass power window motor	\$425.60	?
1 pc	Front n/s door side view mirror	CM \$1,546.70	✓
1 pc	Front n/s door side view mirror cover	mi \$95.10	✓
1 pc	Rear n/s door	Bl/warp \$1,487.60	✓
1 pc	Rear n/s door outer protector	mi \$405.10	✓
1 pc	Rear n/s door inner trim board	Sm \$540.70	X
1 pc	Rear n/s door rubber	Sm \$185.60	X
1 pc	Rear n/s door regulator	\$235.10	?
1 pc	Rear n/s door regulator motor	\$425.60	?
1 pc	Rear n/s door frame black sticker	Me \$85.10	✓
1 pc	N/S rocker panel garnish	Gr \$647.60	✓
1 pc	Front n/s shock absorber	\$455.60	?
1 pc	Front n/s linkage	Sm \$125.60	X
1 pc	Front n/s lower arm	Sm \$635.70	X
1 pc	Front n/s kunckle arm	\$550.30	?
1 pc	Front n/s kunckle arm bearing	\$195.70	?
1 pc	Front n/s hub	\$487.20	?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

balance c/f \$14,166.70

SLS 4117 D

1 pc	Rear n/s shock absorber
1 pc	Rear n/s lower arm
1 pc	Rear n/s trailing arm
1 pc	Rear n/s knuckle arm

balance b/f \$14,166.70

<i>PL</i>	\$425.60	<i>X</i>
<i>PL</i>	\$497.20	<i>X</i>
<i>PL</i>	\$287.60	<i>X</i>
	<u>\$558.20</u>	<i>7</i>

\$14,293.50

Less 25 % \$3,573.38

\$10,720.12

S Nett

2 pcs	Front & rear n/s tyre rim
2 pcs	Front & rear n/s door sticker

<i>nu</i>	\$450.00	\$900.00	<i>✓</i>
		<i>nu</i> \$200.00	<i>16012</i>
		<u>\$1,100.00</u>	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

601
\$1,400.00

To putty & spray paint on accident affected portion.

\$1,400.00 *601*

Check/reconnect wiring.

\$45.00 *201*

To spray anti rust on accident affected portion.

\$180.00 *801*

Remove/refit both front & rear n/s door mechanism, glass to new door

\$200.00 *1201*

Remove/renew front & rear n/s undercarriages

\$480.00 *7*

Check and realign wheel alignment

\$80.00 *601*

Total \$15,605.12

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/07/2023 18:17 (SGT)
Reported by	Actual Driver
Date of Accident	19/07/2023 13:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	NORTH CANAL ROAD TOWARDS CTE/AYE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS4117D
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	L.H CAR RENTAL PTE LTD
Company Reg No	200009761N
Email Address	CARRENTAL.LH@GMAIL.COM
Mobile Phone No	(Phone) +65-82990599
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	C-hr
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMHCSNA00009092300

DRIVER

Name of Driver	CHIA QIN HONG KELVIN
NRIC No	S8514086H
Date Of Birth	04/05/1985
Occupation	Outdoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my work/office and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

LH CAR RENTAL PTE LTD

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Sketch Plan

Vehicle A - SLSA112D

Vehicle B - SLD75062

