

ASS. REC. BY:

REF:

SMO/23007578/Kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBS 2346R

Yr Regn:

02, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Scrambler

Make:

Beta RR

C.C

190

Colour

Multi Colour

A/C:

Insured / Std / NI / NA

Sp.Reading

10398

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ED3EB01C8K 0000655

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

IRC

R:

Pneumax

Jot 100 R21

140/80 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

8

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

22/7/23

D.O.I.

27/7/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S & d/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

In repair cotn @ 4-6K

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$) :

Days Of Repair:

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

S - RS. SI

: Fuel

: Others

TOTAL



SINGAPORE POLICE FORCE



T/20230724/7010

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4

Report No. T/20230724/7010

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
24/07/2023 09:42

Vide Report No.:
E/20230722/0116

Station Diary No.:

Informant's Particulars

Name of Informant: LIN WEN-BIN			Address: 72 TAMAN WARNA SINGAPORE 276392		
ID Type / ID No.: FIN NO / F2475607Q			Contact No.: Home/Office: Mobile: 98240845		
Nationality: TAIWANESE			Email: BENJAMIN.LIN@FMGGLOBAL.COM		
Sex: Male	Age: 61	Date of Birth: 05/11/1961	Type of Informant: Rider		
Race: Chinese			Language: English		
Occupation: Insurance services manager			Driving Licence Information: Class: 2B Date of Expiry: 09/02/2026		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 22/07/2023 16:55	Type of Location: Before no waiting zone box, a bent. no U-turn road divider gap.
Location: ENG NEO AVENUE				
Weather: Sunny		Road Surface: Dry		
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of
FBS2346R	Motorcycle	BETA	RR ENDURO 2T 200	Red		0
SMV957U	Car	TOYOTA		Black		0



SINGAPORE POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20230724/7010

2 of 4

Report No. T/20230724/7010

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBS2346R	NTUC Income Insurance Co-Operative Limited	5121136039-02	24/02/2023	23/02/2024

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL			
Rider		Use of Pedestrian Crossing: NA	
Name	LIN WEN-BIN	ID No.	F2475607Q
Related Vehicle	FBS2346R (Motorcycle)	Contact No.	98240845
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry	Class: 2B Date of Expiry: 09/02/2026
Date	22/07/2023	Date	22/07/2023
No. of Days granted Medical Leave	04	Degree of	Slight

Driver			
Name	TAKAHASHI KENTA	ID No.	M4326387T
Related Vehicle	SMV957U (Car)	Contact No.	98163397
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Brief Details.

Around the above specified time, i.e. 4:55 pm, 22 July 2023, after I riding my bike exited from PIE to Eng Neo Ave. travelling south bound on the right lane toward the junction connecting Bukit Timah/Dunearn Road, at the location where a yellow No Waiting Zone (box) outside of the Orchid Apartment (42 Eng Neo Ave.) or opposite the lamp post (No. 8/with painted words EN1002 at the curb of the opposite travelling direction side of road, a motor car (reg. no. SMV957U) collided to me riding my bike while the driver was veering it to its right where my motorcycle was travelling on. It is noted that the driver (Mr. Takahashi Kenta) of the motor car was attempting to make an U-turn at a location not allowing of such maneuver. The motor car was not standing still and waiting, it was moving and veering off to the right from the left side provided me no enough time to react. except emergency braking and shouting.

After the collision, while I was collecting myself, briefly examined my visible injury, cut/abrasion with blood dripping at my left forearm near the wrist due to the watchband



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20230724/7010

CONTINUATION OF REPORT

when it was torn to snapped, the driver alighted the car and concerned of my condition. After pulsing for 2 to 3 minutes not answering and thought at the time I may be ok, I mentioned "I guess that both of us are very lucky that there may not have big issues to deal with." Although, I am not sure whether he registered what did I say.

There was a lady, believed alighted from a passing by vehicle (Reg. SDK 2838G), asked whether need to call the ambulance/traffic police then she called. Based on the info. (Note: I got from the Para-Medic from the ambulance vehicle, that they got the dispatch call at around 5:00 pm, therefore I believe the incident occurred at around 4:55 pm, etc.) She may witnessed the incident. Another passing by lady, Dr Natalie, a Medical Doctor briefly inspected my injury and also helped to verify "on call 995" whether any ambulance is on the way, she suggested me to have a detail check up, although at the scene she inspected and found generally ok, except the abrasion. Dr. Natalie may also witness the incident.

While waiting for the traffic police to arrive, the ambulance arrived, the female doctor handed over her observation/finding from her inspection of me to the para-medic. As two tow vehicles' staffs suggested to move the vehicle and bike, I then started to take pictures of the scene, including the motor car and my bike involved in this incident. Noticed there were damages to my bike and the impacted condition of the motor vehicle.

The braking mark, believed to be from my bike's tyres, left on the yellow marking material of the "no waiting zone box" indicated my travelling location on the right lane toward my travelling direction. The Traffic Police officer, Mohd Shahzan, mentioned that the driver told him his car have camcorder that may recorded the motor car's travelling dynamic/position and footage at the time of the incident and situation after the impact. The security camera at the gate of the Orchid Apartment with the lens pointing to the road may also have the footage.

My understanding is that the traffic police released my bike to my friends arrived to the scene after left to hospital, to be sent to workshop for damage assessment. The damages noticed then including, but may not limited to handle bar guards, the radiator with the guide vane flew off, my watch was broken, etc. Detail of the damage will need to be assessed by the workshop and insurance company.

I have reported to my motorbike's insurance company INCOME.

The driver of the motor car mentioned that he had reported the incident to his insurance co. and had submitted the recording footage extracted from his car to police on 22 July 2023. He texted me last on 22 July. After I told him I was discharged from hospital and he was relieved to learn that I am generally fine. He expressed his apology for my injury and property damages.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20230724/7010

4 of 4

Report No. T/20230724/7010

CONTINUATION OF REPORT

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPB /
FADLI SHAFUDDIN BIN MOHAMED SANI
Contact No.: 65476845

NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by Singpass. No signature is
required.

Date/Time:
24/07/2023 09:42

Classification Of Case: