

(08/11/13) waf

ASS. REC. BY: John

REF:

CS/SMR 2300 7625/R923

S/ST

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMV 59272at Workshop m/s HAW CAR REPAIRSof 1001 BUNKS MERON LN 3#01-49

Insured:

SMR

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

89K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 58K

Veh No:

SMV 59272

Yr Regn:

2020 / OCTType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit 1.34F CVT c.c 1317

Colour:

grey

A/C: Insured / Std / NI / NA

Sp. Reading

049833

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GR-3342490Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/65R14

R:

cc

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

23/07/23

D.O.I.

31/07/23

Survey held at

HAW CAR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	5151
Vehicle No.:	SMV5927Z
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jul 2023
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3 GF CVT
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	L13B3939390
Chassis No.:	GK33424900
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,850.00
Original Registration Date:	08 Oct 2020
First Registration Date:	08 Oct 2020
Transfer Count:	0
Actual ARF Paid:	\$5,850.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Oct 2030
PARF Rebate Amount:	\$4,387.00
COE Expiry Date:	07 Oct 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,534.00
COE Rebate Amount:	\$26,251.00
Total Rebate Amount:	\$30,638.00

The information contained herein is correct as at 31 Jul 2023

OK

Honda Fit 1.3A GF

\$89,800 Instalment \$904/mth

PREMIUM AD

Shortlist

Loan Calculator



Overview Financial Photo Research

Depreciation	\$12,130 / year
Reg. Date	02-Oct-2020 (7yrs 2mths COE left)
Manufactured	2019
Mileage	31,000 km (11k / year)
Transmission	Auto
Engine Cap	1,317 cc
Road Tax	\$578 / year
Power	73.0 kW (97 bhp) View specs of the Honda Fit
Curb Weight	1,030 kg
COE	\$38,504
OMV	\$15,531
ARF	\$5,531
Dereg Value	\$31,776 as of today
No. of Owners	1