

ASS. REC.
from:
Estimated C
/TP/WS
Inspect Veh
Workshop m

t:
lo.
lo.
red:
Record)
h:
an
dition)
veh has
r at the
alue:
port:

Per
7/

ASS. REC. BY:

REF: CTZ/230076261/Km

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/XP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s Thian 1414

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PKQ 3311

Yr Regn: 07, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy

Privs

C.C

1798

Colour: M Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 298995

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN31U103465833

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size: Maxtex

195/65R15

R: B. J

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 8 mm

L/Bal. 9 mm

L/Bal. 3 mm

D.O.A. 26/7/23

D.O.I. 3/8/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1. ERI NOT READY

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS. SI

Fixtures

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

ump Sum / I.B.I: (\$

TOTAL



SINGAPORE POLICE FORCE



T/20230726/2093

1 of 3

Report No. T/20230726/2093

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
26/07/2023 17:58

Vide Report No.:

Station Diary No.:
95

Informant's Particulars

Name of Informant:
TAN HOI CHEN

Address:
231 PENDING ROAD #04-41 SINGAPORE 670231

ID Type / ID No.:
FIN NO / G6723694M

Contact No.:
Home/Office: Mobile: 86790439

Nationality:
MALAYSIAN

Email:

Sex: Age: Date of Birth:
Female 48 28/09/1974

Type of Informant:
Driver

Race:
Chinese

Language:

Occupation:
clerk

Driving Licence Information:
Class: Date of Expiry:

General Information of the Accident

Type of
Accident:

Injury
Others

Drink
Drive:
No

Date/Time of
Accident:
26/07/2023 14:05

Type of Location:
T-Junction

Location:

CHOA CHU KANG WAY

Weather:
Clear

Road Surface:
Dry

Traffic Flow:
Two Way

Traffic Control:
Not Controlled

Traffic Volume:
Heavy

Type of Collision:
Between Moving Vehicles - Head To Rear

Anyone conveyed by
ambulance:
No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PKQ3311	Car				Slightly Damaged	1
SNC5549U	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE



T/20230726/2093

2 of 3

Report No. T/20230726/2093

Police Station Of Origin:

Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

CONTINUATION OF REPORT

Driver		ID No.	G6723694M
Name	TAN HOI CHEN		
Related Vehicle	NIL	Contact No.	86790439
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 26/7/23 at about 1406hrs, I was waiting at a traffic junction in my vehicle bearing number PKQ3311 of Chua Chu Kang Way as it was a red light, subsequently I felt an impact from the rear of my vehicle, and I noticed a vehicle bearing number SNC5549U front had hit the rear of my vehicle as he had failed to stop in time.

SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

No. Pendaftaran : PK03311

No. ID : 740928025234

Nama Pemunya Berdaftar : TAN HOI CHEN

Alamat : NO 25 JALAN PERMAS JAYA 1/23 TAMAN PERMAS JAYA
81750 MASAI JOHOR

No. Chasis/No. Enjin : JTDKN36U105465833 / 2ZR5462592

Buatan>Nama Model : TOYOTA / TOYOTA PRIUS 1.8L (A) LUXURY

Keupayaan Enjin : 1798

Bahan Bakar : PETROL

Status Asal : KENDERAAN IMPORT BARU

Kelas Kegunaan : PERSENDIRIAN-MOTOKAR INDIVIDU

Jenis Badan/Tahun Dibuat : MOTOKAR / 2012

Tarikh Pendaftaran : 04/07/2012

B. D. M/B. G. K/BTM : -

Syarat Pendaftaran 1 : -

Syarat Pendaftaran 2 : -

Syarat Pendaftaran 3 : -