

ASS. REC. BY: marcus

REF:

CS/ SMO 23007646/UGY3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBN 7957Xat Workshop m/s Unique Motors

of _____

Insured: SYG 73574

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Depline

Vehicle: IN / OUT

Date: _____ Person Contacted: 97678999Veh No: FBN 7957X Yr Regn: 18/12/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Nmax 155 c.c. 155Colour: Grey A/C: Insured / Std / NI / NASp.Reading: Battery flop T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3SG431000009124

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or offroadBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110-70-13R: 130-70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or maxxis

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 08/07/23 D.O.I. 28/7/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S, N/S bodyThe U/C / Chassis frame Body Structure affected due to collision.

Date / Time Action / Instruction

86602358 Jay TOTAL 1055
1.C 8721 LTA 1830
submit TOTAL 1055 3rd Syng. Smth. Dep 1600

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8721

Vehicle Details

Vehicle No.: FBN7957X
Vehicle to be Exported: No
Intended Deregistration Date: 28 Jul 2023
Vehicle Make: YAMAHA
Vehicle Model: NMAX155 ABS
Primary Colour: Grey
Manufacturing Year: 2018
Engine No.: G3H6E0011594
Chassis No.: MH35G431000009124
Maximum Power Output: -
Open Market Value: \$2,514.00
Original Registration Date: 18 Dec 2018
First Registration Date: 18 Dec 2018
Transfer Count: 2
Actual ARF Paid: \$378.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 17 Dec 2028
COE Category: D - Motorcycle
COE Period(Years): 10
QP Paid: \$3,399.00
COE Rebate Amount: \$1,830.00
Total Rebate Amount: \$1,830.00

The information contained herein is correct as at 28 Jul 2023

OK

2024 08-07-23

Sol Syed Smith