

(08/17/20)

ASS. REC. BY: THUAN

REF:

CS31111220070721UCY3

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____

GIA / PR Seen: _____

Est. Repairs: _____

Lum Sum: _____

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

FR: 3h-2h

NO GIA provided

3/7/23 Submit LS \$3300; 4 days (Red \$4200, 56%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Report Format: _____

Lump Sum / I.B.I.: (\$ 3300)Veh No: SMS7124BType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HyundaiColour: blackSp. Reading: 86796Eng/No: hmHD841CMLU029829

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 22/7/22

Survey held at

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 26/8/22 / 1530

26/07/2022

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL