

ASS. REG. BY: Tough

REF:

THU

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report _____

Consistent? : Yes or No

GIA / PR Seer _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lump Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

InsuredVeh No: SHA1867JYr Regn: 2019 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundaic.c. 1580Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading 666481

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 14MHC851 CVR4164303Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. _____

D.O.I. 3/2/23Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Rep. Formist: _____

Lump Sum / L.B.A. /

7/31/23, 2:36 PM

Repairer Estimates

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Jumani (Usun)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	30/07/2023
Vehicle Reg. No.:	SHA1867J	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	26/06/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU295291	Chassis No:	KMHC851CVKU164303
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS	Amount
Parts	1,174.16
Miscellaneous Items	11.00
Labour	750.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,935.16
+ GST 8.00% (S\$)	154.81
Nett Amount (S\$)	2,089.97

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 31 Jul 2023)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA1867J/31/07/2023 14:35**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	df *459.40 FL
2	1		*REAR BUMPER BEAM	20.00	0.00	X *394.80 FL
3	10		*REAR BUMPER CLIPS	20.00	0.00	df *22.00 FL
4	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	df *451.25 FL
5	1		*REAR BUMPER REFLECTOR RH	20.00	0.00	cut *41.45 FL
6	1		*REAR BUMPER TOW COVER	20.00	0.00	X *98.80 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,467.70
- List Item Discount on L Items (S\$)	293.54
Total Parts (S\$)	1,174.16

ComfortDelGro Engineering Pte Ltd/SHA1867J/31/07/2023 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New 350	400.00
2	SPRAYPAINT	New 250	300.00
3	REMOVE/REFIX REVERSE SENSOR	New 30	50.00
Gross Labour Cost (S\$)			750.00

ComfortDelGro Engineering Pte Ltd/SHA1867J/31/07/2023 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tan Jiah 97495749
'wp' 31/7/23 @ 430pm
2/3 Resurvey after repair
Tan Jiah @ LKK Auto
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 31.07.2023 13:50

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5906022

JC NO 305562198

STOMER
/MS COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


COUNT CARD NO.

REGN NO: SHA1867J	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 30.07.2023 16:30
YR OF MANU. 26.06.2019	TARGET DATE
CHASSIS CODE KMHC851CVKU164303	COMPLETION DATE/TIME:

Accident Date: 30.07.2023
Incident Time: 3P.30.07.23

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SHA1867J

JU TOKIO

Vehicle No.:

SHA1867J

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard