

Date: 01/08/2023

Vehicle No: SNC9155X

Model: TESLA MODEL 3 STANDARD RANGE

Chassis: LRW3F7FA8MC385085-2021

Reg.Year: 2021

*Not Authorized
Return by prim
Folow*

Third Party Insurer: MSIG

Third Party Veh No: SLM8713M

Date of Accident: 25/07/2023

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	REAR DOOR RH	1		<i>Ry</i> \$953.27	✓
2	REAR DOOR WEATHERSTRIP RH	1		\$88.79	✓
3	REAR DOOR HANDLE RH	1		\$214.95	✓
4	REAR DOOR LOCK RH	1		\$33.64	✓
5	REAR DOOR INNER TRIM BOARD RH	1		\$560.75	✓
6	REAR DOOR REGULATOR RH	1		\$219.63	✓
7	ROCKER PANEL UNDER COVER RH	1		\$370.00	✓
8	REAR FENDER RH	1		<i>Ry</i> \$1,345.79	✓
9	REAR FENDER QUARTER GLASS RH	1		<i>Ry</i> \$280.37	✓
10	REAR FENDER INNER SHIELD RH	1		\$116.82	✓
11	REAR RIM RH	1		<i>Ry</i> \$939.00	✓
12	REAR ABSORBER RH	1		\$177.57	✓
13	REAR UPPER ARM RH	1		\$18.69	✓
14	REAR LOWER ARM RH	1		\$224.30	✓
15	REAR KNUCKLE ARM RH	1		\$420.56	✓
16	REAR WHEEL BEARING RH	1		\$149.53	✓
17	REAR BUMPER	1		<i>CM</i> \$766.00	✓
18	REAR BUMPER SIDE BRACKET RH	1		<i>DiY</i> \$7.48	✓
19	REAR BUMPER PARKING SENSOR RH	1		<i>Ry</i> \$163.55	X
20	REAR BUMPER PARKING SENSO BRACKET RH	1		<i>Ry</i> \$4.67	X
SUB TOTAL				\$7,055.36	
LESS 10%				-\$705.54	
PARTS TOTAL				\$6,349.82	

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	REAR DOOR INNER TRIM BOARD CLIPS	1		\$50.00	✓
2	ROCKER PANEL UNDER COVER CLIPS RH	1		\$50.00	✓
3	REAR FENDER QUARTER GLASS SEALANT	1		<i>Ry</i> \$80.00	✓
4	REAR BUMPER CLIPS	1		<i>Ry</i> \$50.00	✓
S/N TOTAL				\$230.00	

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 01/08/2023
Vehicle No: SNC9155X
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA8MC385085-2021
Reg.Year: 2021

Third Party Insurer: MSIG
Third Party Veh No: SLM8713M
Date of Accident: 25/07/2023
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC. 8001
\$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH, ROCKER PANEL RH, REAR FENDER RH, REAR BUMPER & ETC. 6601
\$1,000.00

LABOUR CHARGES TO REMOVE & REPLACE REAR FENDER QUARTER GLASS RH, REAR FENDER QUARTER GLASS SEALANT & ETC. TO EFFECT REPLACE OF REAR FENDER RH. \$150.00 601

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM RH, UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH. \$350.00 1001

LABOUR CHARGES TO REMOVE & REPLACE REAR ABSORBER RH, REAR UPPER ARM RH, REAR LOWER ARM RH, REAR KNUCKLE ARM RH, REAR WHEEL BEARING & ETC. \$300.00 7

TO WHEEL ALIGNMENT & BALANCING. \$80.00 201

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER PARKING SENSOR & ETC. \$120.00 601

TO TUFF KOTE & UNDERSEAL MATERIALS. \$150.00 301

TO DIAGNOSIS FAULT CODE & RESET MEMORY. \$150.00 7

TO CHECK WIRING & ELECTRICAL SYSTEM. \$120.00 201

LABOUR TOTAL **\$3,420.00**

TING AN

TOTAL

\$9,999.82

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011



Lump Sum / 1 B 1

3
A
A

99

20

mf
m
2

6m

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	01/08/2023 11:32 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	25/07/2023 21:35 (SGT)
Exact Location of Accident	Tanjong Rhu, Singapore
Additional Location Information	TANJONG RHU ROAD TOWARDS MOUNTBATTEN ROAD (BESIDE SWIMMING CLUB)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNC9155X
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	MANJIT SINGH GREWAL
NRIC No	SXXXX502A
Email Address	MANJITGR@GMAIL.COM
Mobile Phone No	(Phone) +65-84578055
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Tesla
Model	MODEL 3 STANDARD RANGE
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1999

INSURANCE COMPANY

Name of Insurance Company	ECICS Limited
Policy Number / Cover Note Number	MPC22A00213300

DRIVER

Name of Driver	MANJIT SINGH GREWAL
NRIC No	SXXXX502A
Date Of Birth	05/12/1950

Vehicle Registration Number	SLM8713M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
NRIC No	CHANG SHUWEN
Contact Number	SXXXX599C
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




[Handwritten signature]

[Handwritten signature]
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A = SNC9155X
B = SLM8713M

Tanjong Rhu Road
towards
Mountbatten Road
(Beside Swimming Club)