

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 01/08/2023 11:32 (SGT)
Reported by Both Policyholder and Actual Driver
Date of Accident 25/07/2023 21:35 (SGT)
Exact Location of Accident Tanjong Rhu, Singapore
Additional Location Information TANJONG RHU ROAD TOWARDS MOUNTBATTEN ROAD
(BESIDE SWIMMING CLUB)
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SNC9155X

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner MANJIT SINGH GREWAL
NRIC No SXXXX502A
Email Address MANJITGR@GMAIL.COM
Mobile Phone No (Phone) +65-84578055
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Tesla
Model MODEL 3 STANDARD RANGE
Variant -
Exact purpose for which vehicle was being used at time of
accident Private use
Are you claiming under your own insurance policy for repair to
your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1999

INSURANCE COMPANY

Name of Insurance Company ECICS Limited
Policy Number / Cover Note Number MPC22A00213300

DRIVER

Name of Driver MANJIT SINGH GREWAL
NRIC No SXXXX502A
Date Of Birth 05/12/1950

Occupation	Indoor
Date Of Driving Pass	09/03/2021
Driving experience	2 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-84578055
Alt. Phone Number	-
Email Address	MANJITGR@GMAIL.COM
Address	7 WILKINSON RAOD
Address complement	-
Postcode	436502
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	SURINDER KAUR GREWAL
Gender	Female

PASSENGER 2

Name	YUVRAY SINGH MANN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM8713M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	CHANG SHUWEN
NRIC No	SXXXX599C
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan




A = SNC9155X
 B = SLM8713M
 Tanjung Rhu Road
 towards
 Mountbatten Road
 (Beside Swimming Club)

Describe Circumstances of the Accident

Refer to attached

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

On 25.07.23 at about 21:35 hours, I was travelling along Tanjong Rhu Road towards Mountbatten Road (Beside Swimming Club).

While I was going straight on the right lane, suddenly I felt a great impact and the loud bang from my rear right hand side. When I alighted I realized it was vehicle (B) which came out from Singapore Swimming Club Multi Story carpark. The vehicle (B) without stopping and checking the traffic situation she just drove on and collided onto my rear right hand side portion and caused damages to my vehicle . I wish to state that I had two passengers.

Vehicle (A) : SNC9155X

Vehicle (B) : SLM8713M

























