	_
	ーンではた… こ
ASS, REC. BY:	7 awspin
Maria III	

REF:

usis

ASSIGNMENT

From: Date:	Veh No: PPH 8557 Yr Regn:			
Estimated Cost:	Type: M. Cycle / Bus / Van / Lorry / Taxl / Prime Mover /			
OD (TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or			
To Inspect Vehicle No:	Make: Mercedis Runz (200 c.c			
at Workshop m/s	Colour R/aich A/G: Insured / Std / Ni / NA			
of	Sp.Reading 7-3760 T/Radio; Insured / Std / NI / NA			
Insured:	Eng/No:			
Policy No.	C/NO: WDD 2050776L050472			
Clairns No.	Gen. Cond; Good Fair / Poor / Burnt			
Sum insured: Excess:	Sleering: Inorder Jammed / Leaked / Burnt or			
(Client's Record)	Brake: Inorder/Jammed/Leaked/Bumt or			
Make of Veh:	Modi: NIT / SRM / STD A/Rim or			
	Tyre Size: F: 245/40R/8			
(Policy-Condition)	R:			
Remark The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY /-FS / LIZA / MGC OHTSU / PIR / SUMI /			
repair at the time of inspection.	TOYO / YOKO or			
Bal or Market Value:	Front Rear			
IDAC Accident Roort: Consistent? : Yes or No	R/Bal. Pmm R/Bal. mm			
GIA / PR Seem Consistent? : Yes or No	L/Bal, C mm L/Bat. C mm			
Est Repairs: days Res.: Yes or No	D.O.I. 2/8/230 315ph			
Lum Sum: % 3 Val.: Yes or No	Survey held at SV Wufu.			
CA I REV I REP. I 24HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/G / Rooftop- or			
Vehicle: IN / OUT Date: Person Contacted:	Tie III 6 1 Observe from 1 Provide			
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.			
No Log Card Reper	1 Nonge: \$16000-18000, 9days.			
Dala/Time, File Pass to? : Prell. Report	Days Of Repair:			
	Resurvey No. of Trip: Survey Fee:			
Dale/Time, File Return to?	Transportation:			
2) Add Fee:				
	: Interview (\$)) Photos			
Report Formal:	:Tech. Invs (\$) Others			
Lump Sum/LB.E.C	:Weelend (#			
	TOTAL			





1 of 3 Report No. T/20230727/7020

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/07/2023 13:36		de:	Vide Report No.:	Station Diary No.:	
Informant'	s Particul	ars			
Name of Informant: TAY JING KHE			Address:		
ID Type / ID No.: FIN NO / G2580527K			Contact No.: Home/Office:	Mobile: 90059622	
Nationality: MALAYSIAN			Email: JINGKHE99@GMAIL.COM		
Sex: Male	Age: 30	Date of Birth: 13/07/1993	Type of Informant: Vehicle Owner		
Race: Chinese			Language: English		
Occupation: SALES REPRESENTATIVE		ATIVE	Driving Licence Information: Class:	Date of Expiry:	

	1	lent	
Type of Accident:	Injury Others	Drink Date/Tim Drive: Accident No 27/07/20	: Straight Road
Location:			
BUKIT BATON	(WEST AVENUE 8	Road Surface:	
vvealuel.			
1 10 11 11 11 11 11 11 11 11		Dry	
Clear Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate

Details of Volume Vehicle No.	Туре	Make	Model	Color	Conditio	No of
PPH8557	Car	MERCEDES BENZ	C200	Black		0
SHA8817H	Car	DLINZ				0

Details of Vo	ehicle Insurance			
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
	ETIQA INSURANCE BERHAD	KB927106	30/04/2023	29/04/2024





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

2 of 3 Report No. T/20230727/7020

CONTINUATION OF REPORT

Details of Perso	n Involved	13. 15. 15. 15. 15. 15. 15. 15. 15. 15. 15		* +		
Any Pedestrian I	nvolved: No					
No. of Pedestriar	ns Injured: NIL		Use of Pe	Pedestrian Crossing: NA		
Vehicle Owner			The state of the s			
Name	TAY JING KHE		ID No		G2580527K	
Related Vehicle	PPH8557 (Car)			Contact No.		90059622
Hospital/Clinic	NIL			Class of Driving Licence & Expiry		Class: NIL Date of Expiry: NIL
Date	27/07/2023		Date			/2023
No. of Days granted Medical Leave 03			Degree of			

Brief Details.

On the stated date and time. I, Vehicle A (PPH8557) was travelling straight on Lane 4 of Bukit Batok Road Opposite Block 433A. When the front vehicle slowed down and stop, i followed suit without having any collision with the front vehicle. Suddenly, i felt a huge impact from the rear portion of my vehicle after i alighted i then realise that is Vehicle B (SHA8817H) that had collided onto my stationary vehicle. I wish to state that i felt 2 impact the Vehicle B (SHA8817H) hit my car twice.

Due to the huge impact i was injured with neck, shoulder, back and mouth pain. I went to consult a doctor @ Internedical Kovan and was given 3days mc.