

ASS. REC. BY:

REF:

SMR/ 23007828/Kn

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

102k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.1.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SMP 2021 MYR Regn: 09, 19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Airtis

c.c. 1598

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

9209

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR053REH80459787

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

29/7/23

D.O.I.

2/8/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



Prell. Report

1)

Date/Time, File Return to?



Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Report Format :

Interview (\$



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SMP 2021 M

Parts (a) Cost / List Price Items

Plus/Less 25%

Total of Cost / List

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

Total Parts Cost

Labour

\$ 4,120.00

Total

The above total will be subjected to 7% G.S.T.

*Not authorized
Payment By payee*

Name of Surveyor

Hennery

Company

UIC

Survey conducted on

21/8/23

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : *05* day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

De

Date: *21/8/23*



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200006485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SMP2021M

TOYOTA COROLLA ALTIS 1.6 STANDARD
MR053REH604597871

Submit By :

Year Manufacture :

Engine No. :

16-Sep-19

1ZR0D79750

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH front door <i>Rh</i>	1			✓
2	RHF door glass outer moulding <i>Rh</i>	1			✓
3	RH rear door <i>Rh</i>	1			✓
4	RH rear door hinge top <i>Rh</i>	1			X
5	RH rear door hinge bottom <i>Rh</i>	1			X
6	RH rear door weatherstrip <i>Rh</i>	1			X
7	RH rear door trim <i>Rh</i>	1			X
8	RHR door glass outer moulding <i>Rh</i>	1			X
9	RHR power window motor <i>Rh</i>	1			X
10	RHR power window regulator <i>Rh</i>	1			X
11	RH rear fender <i>Rh</i>	1			X
12	RH rear rim <i>Rh</i>	1			✓
13	RH rear tyre	1	\$350.00	S.N	?
14	Rear bumper	1			?
15	Rear bumper clip	10			?
16	Rear bumper side retainer LH <i>Rh</i>	1			X
17	Rear bumper side retainer RH <i>Rh</i>	1			X
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200006486N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Labour

Vehicle No. : **SMP2021M** Submit By : **JENNY**
Make & Model : **ROLLA ALTIS 1.6 STANDARD** (Year of Manufacture : **16-Sep-19**)

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(RHF DOOR,RHR DOOR,RHR FENDER,RHS ROCKER PANEL,REAR BUMPER)	\$1,400.00	800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(RHF DOOR,RHR DOOR,RHR FENDER,RHS ROCKER PANEL,REAR BUMPER)	\$1,200.00	800
3	To do wheel alignment.	\$120.00	60
4	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.(RHF DOOR,RHR DOOR)	\$300.00	120
5	To tuff coat.	\$150.00	80
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
7	To check wiring	\$50.00	20
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$120.00	X
9	To remove & refit rear windscreen. <i>nn</i>	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : SMP2021M

Make & Model : ROLLA ALTIS 1.6 STANDARD Submit By : Carmen Lim
S/N : 43724 Year of Manufacture : 2021

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 01/08/2023 17:01 (SGT)
Reported by Both Policyholder and Actual Driver
Date of Accident 29/07/2023 14:00 (SGT)
Exact Location of Accident 20 Mandai Lake Rd, Bird Paradise, Singapore 729825
Additional Location Information At the Roundabout
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMP2021M

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner GOLDBELL CAR RENTAL PTE LTD
Company Reg No 2XXXXX651D
Email Address accident@gbcr.com.sg
Mobile Phone No (Phone) +65-66039398
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Toyota
Model Corolla
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1598

INSURANCE COMPANY

Name of Insurance Company Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number 23-MAA00173-R00

DRIVER

Name of Driver KOJIMA NAOTO
Passport No/FIN MXXXX694L
Date Of Birth 14/04/1983
Occupation Indoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to invalidate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the Insurer to the GIA Roadside Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will form to be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyer/solicitor firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of my correspondence packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/solicitor firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyer/solicitor firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
Policyholder's Signature / Date & Time

[Signature]
Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]
Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card) **SOH JIT HOON**
Rec'd 01 AUG 2023

Sketch Plan



① I enter into a roundabout

② I drive in outer lane

③ I pass the 1st Exit

④ Taxi, being in inner lane, hit my car.