



**GARAGE 13 PTE LTD**  
8 KAKI BUKIT AVE 4  
#02-54/55 PREMIER@KB  
SINGAPORE 415875  
UEN GST REG NO. 202005684D

31<sup>st</sup> July 2023

Our Ref: GBJ8926A  
Your Ref: SHD3681Z

HSBC Life (Singapore) Pte. Ltd.  
**Motor Claims Department**  
38 Beach Road  
#03-11, South Beach Tower  
Singapore 189767

Dear Sirs,

**ACCIDENT INVOLVING GBJ8926A AND SHD3681Z ALONG GAMBAS AVE TWDS WOODLANDS L/P 121F ON 22.08.2022**

We are the representative for Siang Hock Car Rental Pte Ltd, whose vehicle registration number **GBJ8926A** was damaged in the above accident.

We are instructed to claim for damages against your insured in connection with the above-captioned road traffic accident driven by your insured.

We are instructed that the accident was caused by your insured's negligence and/or management of motor vehicle registration **SHD3681Z**. As a result of the accident, our client's vehicle was damaged and our client had been put to loss and expense, particulars of which are as follows: -

|                                      |    |                  |
|--------------------------------------|----|------------------|
| Cost of repairs                      | \$ | 15,984.00        |
| Loss of use for 16 days @ \$120/day  | \$ | 1,920.00         |
| Survey report                        | \$ | 978.48           |
| LTA search fee                       | \$ | 7.45             |
| 3 <sup>rd</sup> party GIA search fee | \$ | 31.00            |
|                                      | \$ | <u>18,920.93</u> |

Enclosed are the supporting documents for your perusal: -

GIA  
Repair bill

Kindly let us have your payment of **\$18,920.93** in our workshop's name within the next 14 days.

Please do not hesitate to contact our Ms Goh at 6385 1171 or email [msgoh@iaconsulting.sg](mailto:msgoh@iaconsulting.sg) should you have any queries on your matter. We thank you for your kind attention and appreciate your quick remittance.

Yours faithfully,

Encl.

# GARAGE 13

8 Kaki Bukit Ave 4  
Premier @ Kaki Bukit #03-46  
Singapore 415875  
Company Reg Number: 202005684D

## LETTER OF AUTHORISATION

I/We, SIANG HOCK CAR RENTAL PTE LTD. ("the third party claimant")  
of NRIC/FIN/UEN No. 201538271R, owner of vehicle no. GBJ 8926 A. hereby authorize  
M/s GARAGE 13 PTE LTD. ("the workshop") to my claim for repair cost  
and/or rental and/or loss of use and/or survey fee ("claim") for my vehicle no. GBJ 8926 A. that  
was damaged pursuant to the accident which occurred on 20/8/22 (1200HRS) along  
GAMBAS AVE TWP WOODLANDS - L/P 121F involving vehicle no/s  
JHD 3681 Z. ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/ owner/ insurers of the other vehicle/s is concerned.

Dated this 22 (day) of 8 (month) 22 (year)

\*

  
  
SIGNATURE OF OWNER/ COMPANY STAMP (IF APPLICABLE)

> Back to OneMotoring



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 23 Aug 2022 / 10:53:35

Receipt Date/Time : 23 Aug 2022 / 10:53:35

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-220823-001039

Previous Receipt No. :

| S/N | Item Description/<br>Business Transaction Reference<br>No. | Amount<br>Before<br>GST (\$) | GST<br>Amount<br>(\$) | Amount<br>After GST<br>(\$) |
|-----|--|------------------------------|-----------------------|-----------------------------|
|-----|--|------------------------------|-----------------------|-----------------------------|

Result of Insurance Enquiry - SHD3681Z

As at 22 Aug 2022/12:20:00

Insurance Co: AXA INSURANCE PTE LTD

|   |   |      |      |      |
|---|---|------|------|------|
| 1 | Insurance Enquiry - SHD3681Z<br>Enquiry Fee<br>20220823105246510803 | 7.00 | 0.49 | 7.49 |
|---|---|------|------|------|

**Sub-Total** 7.00 0.49 7.49

**Total Before Rounding** 7.00 0.49 7.49

**Rounding Difference** 0.04

**Total Amount Payable** 7.45

Paid By  
549834XXXXXX8101 eNETS Credit Card 7.45

Total 7.45

Cash Change 0.00

Tendered Amount 7.45

Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



RECORD MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

## TAX INVOICE

Date of Request: 26/08/2022

Your Ref No: GBJ 8926 A 3P REPORT

Dear Sir/Madam,

Date of Accident: 22/08/2022 00:00 (SGT)

Vehicle No: GBJ8926A

Place of Accident: Gambas Ave, Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

| DOCUMENTS                        | ACCIDENT LOCATION     | PER DOC (S\$) | QTY | AMOUNT (S\$) |
|----------------------------------|-----------------------|---------------|-----|--------------|
| SHD3681Z                         | Gambas Ave, Singapore | (31.00)       | 1   | (28.97)      |
| GST Amount                       |                       |               |     | (2.03)       |
| Total Amount Due (GST Inclusive) |                       |               |     | (31.00)      |

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.



# Impact Analysis Consulting Pte Ltd

Practicing Management Consultant (PMC) of SBACC  
Approved Training Organisation (ATO) of Workforce Singapore

60 Jalan Lam Huat  
#01-22/23 Carros Centre  
Singapore 737869  
GST Reg no. 201629414D  
Hotline: 6385 1171

Our reference: 23 - 171438

Date: 25-07-2023

**INVOICE NO. 171438**

**Siang Hock Car Rental Pte Ltd**

c/o Garage 13 Pte Ltd  
8 Kaki Bukit Ave 4  
#02-55 Premier@KB  
Singapore 415875

Registration No. **GBJ8926A**

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

| S/No. | Description of Services Provided  | Qty                 | Amount           |
|-------|---|---------------------|------------------|
| 1     | Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous. | 1                   | \$ 906.00        |
|       |   | 8% GST              | \$ 72.48         |
|       |   | <b>Total amount</b> | <b>\$ 978.48</b> |

Please kindly cross all cheques made payable to " Impact Analysis Consulting Pte Ltd ".

We thank you in anticipation for your prompt payment.



**L. L. Tan (Ms)**  
Principal Consultant

*Subsidiaries of Impact Analysis:*

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd  
[www.iaconsultingsg.com](http://www.iaconsultingsg.com)

Our reference: 23 - 171438

Date: 25-07-2023

c/o Garage 13 Pte Ltd  
8 Kaki Bukit Ave 4  
#02-55 Premier@KB  
Singapore 415875

Dear Sirs

**RE: Road Traffic Accident on 22/8/2022**  
**Siang Hock Car Rental Pte Ltd**

In accordance with your instructions received in this office on **25/8/2022**, we made arrangements to examine the vehicle on **25/8/2022** at above-mentioned address. The following data was recorded:

#### Vehicle details

|           |                    |              |                   |
|-----------|--------------------|--------------|-------------------|
| Make      | VOLKSWAGEN         | Registration | GBJ8926A          |
| Model     | T6 VAN TDI NWB DSG | Chassis      | WV1ZZZ7HZKH032285 |
| Colour    | Red                | Gearbox      | Auto              |
| Odometer  | *                  | Paintwork    | Fair              |
| Steering  | In order           | Brakes       | In order          |
| Condition | Fair               |              |                   |

#### Tyre Depths

|             |            |              |
|-------------|------------|--------------|
| Front left  | 215/65R16C | 85% Sailwin  |
| Front right | 215/65R16C | 85% Sailwin  |
| Rear left   | 215/65R16  | 85% Greenmax |
| Rear right  | 215/65R16  | 85% Greenmax |

#### Impact Direction & Area of Damage:



|              |              |
|--------------|--------------|
| Status       | REPAIRABLE   |
| Magnitude    | Medium       |
| Legal status | Unroadworthy |

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$14,800.00 and 12 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis:

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd  
[www.iaconsultingsg.com](http://www.iaconsultingsg.com)

Our reference: 23 - 171438

Date: 25-07-2023

Page 2

### Section A: Damaged Parts Assessment

| Part's Description                       | Qty | Condition As inspected | Repairer's Estimate | Our Adjustment |
|--|-----|------------------------|---------------------|----------------|
| <b>List Items :</b>                      |     |                        |                     |                |
| Bonnet                                   | 1   | buckled                | 1875.00             | 1875.00        |
| Bonnet lock                              | 1   | bent                   | 192.00              | 192.00         |
| Bont catch                               | 1   | refix                  | 112.50              | 0.00           |
| Bonnet damper                            | 1   | bent                   | 112.50              | 112.50         |
| Bonnet hinge @\$157.50                   | 2   | bent                   | 315.00              | 315.00         |
| Bonnet insulation                        | 1   | crumpled               | 248.00              | 248.00         |
| Front bumper                             | 1   | deformed               | 1620.00             | 1620.00        |
| Front bumper chrome moulding             | 1   | dented                 | 112.00              | 112.00         |
| Front bumper lower side garnish rh       | 1   | deformed               | 172.00              | 172.00         |
| Front bumper side bracket rh             | 1   | broken                 | 122.00              | 122.00         |
| Front bumper side retainer rh            | 1   | broken                 | 37.80               | 37.80          |
| Front bumper inner support bracket       | 1   | broken                 | 255.00              | 255.00         |
| Front bumper reinforcement               | 1   | distorted              | 835.00              | 835.00         |
| Headlamp @\$835.00                       | 2   | grazed.cracked         | 1670.00             | 1670.00        |
| Front fender rh                          | 1   | repair.respray         | 910.50              | 0.00           |
| Front support panel                      | 1   | broken                 | 1270.00             | 1270.00        |
| Front subframe                           | 1   | bent                   | 2350.00             | 2350.00        |
| Air intake hose                          | 1   | broken                 | 76.50               | 76.50          |
| Radiator air guide rh                    | 1   | deformed               | 48.00               | 48.00          |
| Radiator                                 | 1   | ruptured               | 1016.00             | 1016.00        |
| Radiator top hose                        | 1   | necessary              | 67.50               | 67.50          |
| Radiator bottom hose                     | 1   | necessary              | 135.00              | 135.00         |
| Inter cooler                             | 1   | ruptured               | 986.00              | 986.00         |
| Inter cooler hose @\$220.00              | 2   | refix                  | 440.00              | 0.00           |
| Air con condenser                        | 1   | ruptured               | 1465.00             | 1465.00        |
| Air con compressor to cut off point pipe | 1   | bent                   | 156.00              | 156.00         |

Our reference: 23 - 171438

Date: 25-07-2023

|                                  |   |                     |                 |                 |
|----------------------------------|---|---------------------|-----------------|-----------------|
| Radiator fan cowling             | 1 | cracked             | 326.40          | 326.40          |
| Radiator fan motor               | 1 | cracked.malfunction | 1820.00         | 1820.00         |
| <b>Sub- Total cost</b>           |   |                     | <b>18745.70</b> | <b>17282.70</b> |
| Percentage discount : 10%        |   |                     | 1874.57         | 1728.27         |
| <b>Sub-Total costs for parts</b> |   |                     | <b>16871.13</b> | <b>15554.43</b> |

#### Special Nett Items:

|                                  |     |           |               |               |
|----------------------------------|-----|-----------|---------------|---------------|
| Bonnet Company sticker           | 1   | necessary | 220.00        | 220.00        |
| Bonnet insulation clip           | set | necessary | 30.00         | 30.00         |
| Front bumper clip                | set | necessary | 50.00         | 50.00         |
| Front number plate with casing   | 1   | dented    | 50.00         | 50.00         |
| <b>Sub-Total costs for parts</b> |     |           | <b>350.00</b> | <b>350.00</b> |

#### **Parts Repair**

|                              |   |   |                 |                 |
|------------------------------|---|---|-----------------|-----------------|
| *                            | * | * | 0.00            | 0.00            |
| <b>Sub- Total costs</b>      |   |   | <b>0.00</b>     | <b>0.00</b>     |
| <b>Total costs for parts</b> |   |   | <b>17221.13</b> | <b>15904.43</b> |

Our reference: 23 - 171438

Date 25-07-2023

Page 3

### Section B: Labour Cost Calculation

|  | Hourly rate        | Manhr. Req. | Total              |
|--|--------------------|-------------|--------------------|
| To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts. | \$ 45.00           | 26          | \$ 1,170.00        |
| Putty & Spray painting to adjacent panels. Job allowance. Paint / material.  | Sub-contract work. |             | \$ 750.00          |
| Apply rust proofing on the adjacent panels.  | Sub-contract work. |             | \$ 40.00           |
| Remove / replace aircon condenser and refill aircon gas  | \$ 45.00           | 2.5         | \$ 112.50          |
| Remove / refix radiator, top up coolant & conduct pressure test  | \$ 45.00           | 2           | \$ 90.00           |
| Remove and replace front subframe  | \$ 45.00           | 8           | \$ 360.00          |
| Specialist charges - Wheel alignment   | -                  | -           | \$ 60.00           |
| Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)  | \$ 45.00           | 1           | \$ 45.00           |
| <b>Total labour cost</b>   |                    |             | <b>\$ 2,627.50</b> |

*Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.*


Our reference: 23 - 171438

Date 25-07-2023

## Section C: Summary Table of Total Repair Cost

| Description   |            | Cost        |
|---|------------|-------------|
| <b>Damaged Parts Assessment</b><br><i>(See section A)</i> |            | \$15,904.43 |
| <b>Labour Cost Calculation</b><br><i>(See section B)</i>  |            | \$2,627.50  |
| <b>Total cost</b>   |            | \$18,531.93 |
| <b>Lump Sum</b>   |            | \$3,706.39  |
| <i>Further discount</i>                                   | <b>20%</b> |             |
| <b>Total Repair Cost</b>                                  |            | \$14,800.00 |

We would recommend a sum of \$14,800.00 and 12 working days for repair.  
No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.

  
Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)  
B.Eng. (Hons, NUS)  
Diploma.Mechanical Engineering  
NTC-2 Automovite Technology  
Sr.MIES, Institution of Engineers, Singapore (#20100091)  
MATAI, Maryland Association of Traffic Accident Investigators  
IAARS, International Association of Accident Reconstruction Specialists  
PMC of Singapore Business Advisors & Consultants Council  
ACTA certified Trainer, Singapore  
Enterprise Singapore - Recognised Certification for Management Consultants  
IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)

Subsidiaries of Impact Analysis:

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd  
www.iaconsultingsg.com























































































# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

|                                 |                                    |
|---------------------------------|------------------------------------|
| Date of Submission              | 25/08/2022 15:40 (SGT)             |
| Reported by                     | Driver                             |
| Date of Accident                | 22/08/2022 12:20 (SGT)             |
| Exact Location of Accident      | Singapore                          |
| Additional Location Information | GAMBAS AVE TWDS WOODLANDS L/P 121F |
| Country/State of Loss           | Singapore                          |

## DETAILS OF OWN VEHICLE

|                             |                               |
|-----------------------------|-------------------------------|
| Vehicle Registration Number | GBJ8926A                      |
| INSURED/POLICYHOLDER        |                               |
| Is company?                 | Yes                           |
| Name Of Registered Owner    | SIANG HOCK CAR RENTAL PTE LTD |
| Company Reg No              | 201538271R                    |
| Email Address               | car.rental@sianghock.com.sg   |
| Mobile Phone No             | (Phone) +65-62568888          |
| Alternative Phone No        | -                             |

## VEHICLE PARTICULARS

|  |                           |
|--|---------------------------|
| Manufacturer   | Volkswagen                |
| Model  | T6 VAN TDI NWB DSG        |
| Variant  | -                         |
| Exact purpose for which vehicle was being used at time of accident           | Employment                |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category   | Commercial vehicle        |
| Transmission   | Manual                    |
| CC   | 1968                      |

## INSURANCE COMPANY

|                                   |                                |
|-----------------------------------|--------------------------------|
| Name of Insurance Company         | MS First Capital Insurance Ltd |
| Policy Number / Cover Note Number | D-22099203MFCV/216             |

## DRIVER

|                |              |
|----------------|--------------|
| Name of Driver | FOO TEE HONG |
| NRIC No        | S6945630H    |
| Date Of Birth  | 29/12/1969   |
| Occupation     | Outdoor      |

|  |                             |
|--|-----------------------------|
| Date Of Driving Pass .....   | 12/01/2001                  |
| Driving experience .....   | 21 YEARS AND 7 MONTHS       |
| Gender .....   | Male                        |
| Mobile Number .....  | (Phone) +65-85110779        |
| Alt. Phone Number .....  | -                           |
| Email Address .....  | car.rental@sianghock.com.sg |
| Address .....  | BLK 172 LOR 1 TOA PAYOH     |
| Address complement .....   | #14-1156                    |
| Postcode .....   | 310172                      |
| Is the driver the policyholder? .....                              | No                          |
| If No, Relationship of the Driver with the Insured .....           | Hirer                       |
| Does Driver Own Other Vehicles? .....                              | No                          |
| Vehicle Registration Number of Other Vehicle Owned by Driver ..... | -                           |
| Insurance Company of Other Vehicle Owned by Driver .....           | -                           |

GENERAL INFORMATION OF THE ACCIDENT

|                          |                               |
|--------------------------|-------------------------------|
| Type of Accident .....   | Collision - Change/cross lane |
| Weather Conditions ..... | Clear                         |
| Road Surface .....       | Dry                           |

OTHER INFORMATION

|   |     |
|---|-----|
| Was any foreign vehicle involved in the accident? .....   | No  |
| Number of vehicles involved in the accident .....   | 2   |
| Was anybody injured in the Accident? .....  | No  |
| Was any injured conveyed to hospital by ambulance? .....  | -   |
| Was any other vehicle or property damaged? .....  | Yes |
| Number of Passengers (Including Driver) .....   | 1   |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? ..... | No  |
| Translator's name .....   | -   |
| Translator's ID .....   | -   |
| Translator's phone number .....   | -   |
| Translator's email .....  | -   |
| Original language used in the statement .....   | -   |

DETAILS OF POLICE ACTION

|   |    |
|---|----|
| Was the accident reported to the police? .....  | No |
| Was notice of intended Prosecution given? ..... | No |
| If yes, against whom? .....                     | -  |

CIRCUMSTANCES OF ACCIDENT

PLS REFER TO THE ATTACHED STATEMENT

ATTACHMENT(S)

|   |     |
|---|-----|
| Are accident photos available for attachment? ..... | Yes |
| Was there any video captured by Car Camera? .....   | No  |

DETAILS OF OTHER VEHICLE PROPERTY 1

|                                   |                 |
|-----------------------------------|-----------------|
| Vehicle Registration Number ..... | SHD3681Z        |
| Vehicle Manufacturer .....        | -               |
| Vehicle Model .....               | -               |
| Vehicle Variant .....             | -               |
| Vehicle Colour .....              | -               |
| Vehicle Category .....            | Taxi            |
| Name of Driver .....              | ABAS BIN OTHMAN |
| NRIC No .....                     | S1794458D       |

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information"), and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Center Personnel

Sketch Plan

GAMBAS AVE TWAS WUALANAS 4/P 121F

*Slym 25/08/22*



**Describe Circumstances of the Accident**

On 22/08/2022 at About 12.20pm I was driving my  
Company Van Vehicle A (GB58926A) ~~at~~ along garbas Ave  
toward ~~road~~ I slow down my vehicle due to Roadwork  
~~ahead~~ ahead suddenly vehicle B (SHD3681D) cut into my lane  
and hit on to me.

**Declaration**

I/we declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

*shym* 25/08/22

Witnessed by Reporting Centre Personnel