

ASS. REC. BY: Taufik

REF:

7M1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seer _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

DumeneVeh No: SHC 7699C Yr Regn: 2 491 NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Lorry c.c. 1580.Colour: Yellow A/G: Insured / Std / NI / NASp. Reading: 361945 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC 851 CV 64185686Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim orTyre Size: F: 175/65R15R: 175/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 2/8/23Survey held at Lumpit Lorry

Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or

Frt N/S

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Page to?

☐ : Prell. Report☐ : Final Report1) _____
Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Wheel-end (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

Rep. Formet: _____

Lump Sum / L.B.A. (\$ _____)

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
59 Loyang Drive
Singapore 508969
Tel: 6214 8300

ICIX
Jumani (Lum)

TP INSURER:
CCPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	02/08/2023
Vehicle Reg. No.:	SHC7699C	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	27/11/2019
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LEKU389018	Chassis No:	KMHC851CVLU183686
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	
Miscellaneous Items	2,980.60
Labour	11.00
Paintwork Labour	1,500.00
Towing	0.00
	0.00
Gross Total (\$\$)	4,491.60
+ GST 8.00% (\$\$)	359.33
Nett Amount (\$\$)	4,850.93

this claim is handled by: JUMANI BIN MASUDIN

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 02 Aug 2023)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC7699C/02/08/2023 15:15**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY	20.00	0.00	de ✓ *481.10 FL
2	10		*FRT BUMPER CLIPS	20.00	0.00	key ✓ *22.00 FL
3	1		*FRT BUMPER CENTRE MOULDING	20.00	0.00	ent ✓ *368.50 FL
4	1		*FRT BUMPER SIDE BRACKET LH	20.00	0.00	? ✓ *35.00 FL
5	1		*HEADLAMP ASSY LH	20.00	0.00	Cur ✓ *2,110.30 FL
6	1		*FRT FENDER LH	20.00	0.00	KY ✓ *588.80 FL
7	1		*FRT FENDER EMBLEM LH	20.00	0.00	rel ✓ *26.60 FL
8	1		*FRT FOG LAMP GRILLE LH	20.00	0.00	X ✓ *93.45 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,725.75
- List Item Discount on L Items (S\$)	745.15

Total Parts (S\$)	2,980.60
--------------------------	-----------------

ComfortDelGro Engineering Pte Ltd/SHC7699C/02/08/2023 15:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New 525	800.00
2	SPRAY PAINT	New 500	600.00
3	CHECK WIRING	New 30	50.00
4	TUFF KOTE	New 207	50.00
Gross Labour Cost (S\$)			1,500.00

ComfortDelGro Engineering Pte Ltd/SHC7699C/02/08/2023 15:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495749
WP 2/8/23 C
USK survey after repair
Tanpin Effkembu
2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 02.08.2023 15:05

Page : 1

am: ARC Repair TP(CFS0)1

JOB CARD Sales Order: 5906423


JC NO305562534

OMER S CITYCAB PTE LTD OMER NO 7010070 IESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65551188 (O) (P) JUNT CARD NO.	REGN NO.: SHC7699C	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G3) 02.08.2023 10:50	DATE/TIME IN
	YR OF MANU. 27.11.2019	TARGET DATE
	CHASSIS CODE KMHC851CVLU183686	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 02.08.2023
 ATURE: 3P.02.08.23

NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Agreement Slip

Exit Pass

Vehicle No.: SHC7699C JU TOKIO

Vehicle No.:

SHC7699C

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection.

To be kept by Security Guard